

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



AUTOMOBILE INSPECTION REPORT						
INCO	ME INSURANCE	LTD	NS/INC23005973/Tvp3m4			
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	22-06-2023		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	YQ 5585K	Veh. Ir	spected	SHD 6649Z	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1227437-002	Exces	s (\$)	0.00	
	Assign From		Assigr	n Date	12/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2020	
	Chassis No.	JTDKB3FU703091555	Coloui	ſ	BLUE	
	Odometer	564338	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65R15	WEST I	LAKE	6 mm	
	L/H Front Tyre	195/65R15	WEST I	LAKE	6 mm	
	R/H Rear Tyre	195/65R15	WEST I	LAKE	6 mm	
	L/H Rear Tyre	195/65R15	WEST I	LAKE	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/06/2023	Inspec	tion Date	12/06/2023	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				