

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23005976/Tvp3e2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	23-06-2023 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SGQ 705C	Veh. Ir	spected	SHD 3490H	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1226701-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	12/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU093475	Coloui	•	BLUE	
	Odometer	817727	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST	_AKE	6 mm	
	L/H Front Tyre	205/60 R16	WEST	_AKE	6 mm	
	R/H Rear Tyre	205/60 R16	WEST	_AKE	6 mm	
	L/H Rear Tyre	205/60 R16	WEST	_AKE	6 mm	
4.	I. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date 08/06/2023 Inspection Date 12/06/2023				12/06/2023	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					