



**COMFORT TRANSPORTATION PTE LTD**

**REPAIR ESTIMATE**

Vehicle No. : SHD8598Z

Make : HYUNDAI

Model : IONIQ(G2)

Date: 12/06/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 481.10 <i>ll</i>
10	FRT BUMPER CLIPS			\$ 22.00 <i>ll</i>
1	FRT BUMPER SIDE BRACKER RH			\$ 28.00 <i>ll</i>
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50 <i>cut</i>
1	HEADLAMP RH			\$ 2,110.30 <i>?</i>
1	FRT BUMPER SIDE MOULDING RH			\$ 93.60 <i>x</i>
1	FRT FENDER RH			\$ 588.80 <i>ll</i>
1	FRT FENDER BLUE-DRIVE EMBLEM RH			\$ 26.60 <i>ll</i>
1	FRT WHEEL COVER RH			\$ 217.20 <i>cut</i>
	<b>SUB TOTAL</b>			\$ 3,936.10
	<b>LESS 20%</b>			\$ 787.22
	<b>DISCOUNTED TOTAL</b>			\$ 3,148.88
				\$ -
	<b>Labour Charge</b>			
	PANEL BEATING			\$ <sup>350</sup> 750.00
	SPRAY PAINTING CHARGE			\$ <sup>500</sup> 600.00
	CHECK ALL LIGHTING			\$ <sup>300</sup> 60.00
	<b>TOTAL LABOUR</b>			\$ 1,410.00
	<b>ESTIMATE TOTAL</b>			\$ 4,558.88

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Tanji 92495749*  
*wr 12/6/23 C 430*  
*- 2 day*  
*L/S Resurvey after repair*  
*Tanji Chhantara*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:

Team: ARC Repair TP(CFSO)1

**JOB CARD** Sales Order: 5899942


JC NO305557510

CUSTOMER  FIRMS CITYCAB PTE LTD CUSTOMER NO. 7010070 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 TEL. (R) 65551188 (O) (P)  DISCOUNT CARD NO.	REGN NO.: SHD8598Z	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G2)	DATE/TIME IN 12.06.2023 13:00
	YR OF MANU. 04.12.2018	TARGET DATE
	CHASSIS CODE KMHC851CVKU115092	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 11.06.2023  
NATURE: 3P 11.06.2023

S/NO                      LABOR CODE                      DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD8598Z                      YY

Vehicle No.: SHD8598Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard