

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC23005982/Tvp3m4	
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	26-06-2023 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKX 266T	Veh. Ir	spected	SHD 7128D
	Policy No.		Covera	age (\$)	0.00
	Claim No.	MT/1227000-002	Exces	s (\$)	0.00
	Assign From		Assign	n Date	12/06/2023
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I40	c.c		1685
	Engine No.	HIDDEN	Year o	f Reg.	2016
	Chassis No.	KMHLB41UMHU096272	Coloui	•	BLUE
	Odometer	818994	Steeri	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60R16	WEST	_AKE	6 mm
	L/H Front Tyre	205/60R16	WEST	_AKE	6 mm
	R/H Rear Tyre	205/60R16	WEST	_AKE	6 mm
	L/H Rear Tyre	205/60R16	WEST	_AKE	6 mm
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/06/2023	Inspec	tion Date	12/06/2023
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				