

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INCOME INSURANCE LTD	DAMAGE ASSESSMENT REPORT							
INCOME CENTRESINGAPORE 189557 ATTN: RODERIC YUEN Code: INC		INCOME INSURAN	ICE LTD		Ref:	CS/INC23005992/Uqy3e2		
Insured Veh. SMN 2143E								
Insured Veh. SMN 2143E		ATTN: RODERIC \	/UEN		Code:	INC		
Policy No.	1.	<u>_</u>						
Claim No. MT/1226945-002 Excess (\$) 0.00 Assign From HAZALYSA Assign Date 13/06/2023 2. Vehicle Particulars & Condition Make & Model TOYOTA WISH (A) c.c 1794 Engine No. HIDDEN Year of Reg. 2008 Chassis No. JTDER12W803000880 Colour SILVER Odometer 183575 KM Steering AFFECTED Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres		Insured Veh.	SMN 2143E	Veh. Inspected	t	SJK 6577L		
Assign From		Policy No.		Coverage (\$)		0.00		
Make & Model		Claim No.	MT/1226945-002	Excess (\$)		0.00		
Make & Model		Assign From	HAZALYSA	Assign Date		13/06/2023		
Engine No. HIDDEN Year of Reg. 2008 Chassis No. JTDER12W803000880 Colour SILVER Odometer 183575 KM Steering AFFECTED Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance	2.	Vehicle Particulars & Condition						
Chassis No. JTDER12W803000880 Colour SILVER		Make & Model	TOYOTA WISH (A)	c.c		1794		
Odometer 183575 KM Steering AFFECTED Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance		Engine No.	HIDDEN	Year of Reg.		2008		
Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance		Chassis No.	JTDER12W803000880	Colour		SILVER		
General GOOD 3. Conditions of Tyres Size		Odometer	183575 KM	Steering		AFFECTED		
3. Conditions of Tyres Size		Brakes	IN ORDER	Modification		SPORTS RIM		
R/H Front Tyre 195/65 R15 MICHELIN 6 mm L/H Front Tyre 195/65 R15 MICHELIN 6 mm R/H Rear Tyre 195/65 R15 MICHELIN 6 mm L/H Rear Tyre 195/65 R15 MICHELIN 6 mm L/H Rear Tyre 195/65 R15 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. 5. General Information Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		General	GOOD					
R/H Front Tyre 195/65 R15 MICHELIN 6 mm L/H Front Tyre 195/65 R15 MICHELIN 6 mm R/H Rear Tyre 195/65 R15 MICHELIN 6 mm L/H Rear Tyre 195/65 R15 MICHELIN 6 mm L/H Rear Tyre 195/65 R15 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. 5. General Information Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339, EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	3.	. Conditions of Tyres						
L/H Front Tyre 195/65 R15 MICHELIN 6 mm R/H Rear Tyre 195/65 R15 MICHELIN 6 mm L/H Rear Tyre 195/65 R15 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. 5. General Information Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair			Size	Make		Balance		
R/H Rear Tyre 195/65 R15 MICHELIN 6 mm L/H Rear Tyre 195/65 R15 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. 5. General Information Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		R/H Front Tyre	195/65 R15	MICHELIN		6 mm		
L/H Rear Tyre 195/65 R15 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. 5. General Information Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		L/H Front Tyre	195/65 R15	MICHELIN		6 mm		
4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. 5. General Information Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339, EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		R/H Rear Tyre	195/65 R15	MICHELIN		6 mm		
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. 5. General Information Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		L/H Rear Tyre	195/65 R15	MICHELIN		6 mm		
UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. 5. General Information Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	4.		Description of Damages					
Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		UNDERCARRIAGE AFFECTED DUE TO COLLISION.						
Accident Date 10/06/2023 Inspect Date / Time 13/06/2023 (12:39 PM) Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	5		Ganaral Information					
Survey held at ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	J.	Accident Date		1	Time	13/06/2023 (12:39 PM)		
130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair								
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		Jan 197 Hold at	#08-1339,EUNOS SPRING					
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	5a.		Remarks					
, ,								
ESTIMATED MODIMAL DEDICE FOR DEDAID.	5b.		r ·					
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days		ESTIMATED NORI						