



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: CHRYLLIS QUAH

Ref: CS/INC23005993/Uqy3m4

Date: 06/07/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKL 1934E	Veh. Inspected	SCY 6006C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1226992-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	13/06/2023

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C200 AMG LINE (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2050422R282603	Colour	GREY
Odometer	126202 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/35 ZR19	CONTINENTAL	6 mm
L/H Front Tyre	235/35 ZR19	CONTINENTAL	6 mm
R/H Rear Tyre	265/30 ZR19	CONTINENTAL	6 mm
L/H Rear Tyre	265/30 ZR19	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/06/2023	Inspect Date / Time	13/06/2023 (12:54 PM)
Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**