

(08/11/13) wef

REF:

CS/CTI 23006004/Rnp3

259H

ASS. REC. BY: AME

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNJ 3251D

at Workshop m/s GOLDARU

of 8, TURN MRL8

Insured: CTI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lam Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SNJ 3251D Yr Regn: 2023 / JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: OPEL CORSA-E c.c. \_\_\_\_\_

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 15346 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VXKUH2KSZN4358827

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 27/05/23

D.O.I. 14/06/23

Survey held at GOLDARU

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)



**Motorviva Pte Ltd**  
A member of Goldbell Engineering

**MOTORVIVA PTE LTD**

Main Office: 8 Tuas Ave 18 Singapore 638892 Tel: 6665 2518  
Finance: 8 Tuas Ave 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500  
Showroom: 48 Changi South Street 1 Level 3 Singapore 486130 Tel: 6665 2518 Fax: 6561 7956  
Iveco: 8 Tuas Ave 18 Singapore 638892 Tel: 6863 6864 Fax: 6861 3676  
Website: www.motorviva.com.sg  
Co. Reg. No.: 199507614Z

DATE : 7/6/2023  
TO : China Taiping Insurance  
ATTN : Motor Survey  
OFFICE / MOBILE :  
EMAIL ADDRESS :

VEHICLE NO. : SNJ3251D  
MODEL NO. : CORSA-E  
CHASSIS NO. : VXKUHZKSN4358  
ENGINE NO. : NA  
REG. DATE : 11 Jan 2023

FROM : Goldbell Motor Claims  
ATTN : Ramesh  
OFFICE / MOBILE : 81578014  
FAX NO. :

REF. NO. :  
D.O.A : 27/5/2023  
POLICY NO. :  
CLAIM TYPE : Third Party Claim

WORKSHOP : Goldbell TUAS

S/N	PART NO.	DESCRIPTION	QTY	Parts Cost	Nett Price	Canni Parts
1	166335711T	Rear bumper cover <i>de-</i>	1	\$ 966.19		
2	98 295 437 80	Rear bumper cover end bracket right <i>X</i>	1	\$ 131.26		
3	98 295 438 80	Rear bumper cover end bracket left <i>X</i>	1	\$ 131.26		
4	98 295 434 80	Rear bumper cover absorber <i>X</i>	1	\$ 160.74		
5	98 295 267 80	Rear bumper cover reinforcement absorber <i>X</i>	1	\$ 600.71		
6	98 293 336 80	Rear bumper cover bracket right <i>X</i>	1	\$ 131.26		
7	98 293 335 80	Rear bumper cover bracket left <i>X</i>	1	\$ 131.26		

SUB-TOTAL : \$ 2,252.68

**SPECIAL -NETT ITEMS**

1	Rear RHS fender BlueSG sticker <i>X</i> (Based on supplier invoice + 10%)	\$ 165.00
---	--	-----------

PARTS TOTAL : \$ 165.00

**LABOUR CHARGES**

1	To panel beat and repair Rear Fender RH <i>\$</i>	\$ 925.00 <i>* 200</i>
2	To paint Rear Bumper and Rear Fender RH <i>X</i>	\$ 1,300.00 <i>200</i>
3	To deactivate & activate EV safety switch for repairs. <i>X</i>	\$ 150.00 <i>X</i>
4	Towing Charge <i>receipt</i>	\$ 55.00 <i>?</i>

LABOUR TOTAL : \$ 2,430.00

TOTAL : \$ 4,847.68

8% GST \$ 387.81

GRAND TOTAL : \$ 5,235.49

PREPARED BY : \_\_\_\_\_

CUSTOMER  
CONFIRMED &  
ACCEPTED BY : \_\_\_\_\_

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Company Stamp : \_\_\_\_\_

*Ramesh*  
*Hy 500106K*  
*2 days*  
*P/P*  
*14/06/23 @ 1145*  
*Resy by paint*



**IVECO**



Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	259H
Vehicle Details	
Vehicle No.:	SNJ3251D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Jun 2023
Vehicle Make:	OPEL
Vehicle Model:	CORSA-E
Primary Colour:	White
Manufacturing Year:	2022
Engine No.:	-
Chassis No.:	VXKUHZKSZN4358827
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$29,361.00
Original Registration Date:	11 Jan 2023
First Registration Date:	11 Jan 2023
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2033
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2033
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$80,000.00
COE Rebate Amount:	\$64,000.00
<b>Total Rebate Amount:</b>	<b>\$64,000.00</b>

The information contained herein is correct as at 08 Jun 2023

OK