




Service Request Details

Claim

S3M04N88

Reference

CS3/HSB23006006/p3 

Loss Date

8 June 2023

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

12 Jun 2023 12:47:00 PM

Request Date

13 June 2023

Due Date

13 June 2024

Services

Pre-Repair Survey

Actions

Next Step

Complete work

More ▼

Vehicle Information

Incident Vehicle Registration #

SMD2476Y

Make

TPVD BMW

Model

116d

Service Address

'''

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188


Claim Handler

LOW Garnet

garnet.low@axa.com.sg

Additional Instructions

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

TYPE 

SENT 13/6/23 5:39 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT [Assignment](#)

BODY [Dear Sir/Mdm, Thank you for the assignment. Please...](#)

