

(08/11/13) wef

ASS. REC. BY: J. Am

REF: CS3/11123002118/Rvg3-1

1411

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV


To Inspect Vehicle No: SNC 8018Rat Workshop m/s JCM RENTLof 1, BUILT BARRAC CRESCENT #04-40Insured: SLL 681D 111Policy No. D21MFL0000447_02Claims No. MFL2023D0002377

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 80K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC 8018R Yr Regn: 2018 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda FIT Hybrid 1.5 A c.c. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: APS1330187Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / 8/Rim / STD A/Rim orTyre Size: F: 185/60R15R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KAPSEN

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 23/02/23Survey held at JCM

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 27/02/23

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR & REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 55KESTIMATE RANGE OF REPAIR / NO. OF DAYS - 15K-16K / 11-12 days

17/7/23 Submit LS \$13,450 (Red 4750, 26%)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 6/3/23-typist17/7/23-typist

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 12

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1411
Vehicle Details	
Vehicle No.:	SNC8018R
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Mar 2023
Vehicle Make:	HONDA
Vehicle Model:	FIT HYBRID 1.5 AUTO
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	LEB1436328
Chassis No.:	GP51330187
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$18,986.00
Original Registration Date:	22 Nov 2018
First Registration Date:	22 Nov 2018
Transfer Count:	2
Actual ARF Paid:	\$8,986.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Nov 2028
PARF Rebate Amount:	\$6,739.00
Intended COE Rebate Details	
COE Expiry Date:	21 Nov 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,101.00
COE Rebate Amount:	\$17,762.00
Total Rebate Amount:	\$24,501.00

Honda Fit Hybrid 1.5A

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$79,800****Depreciation** ⓘ**\$13,410 /yr**[View models with similar depre](#)**Reg Date****31-Oct-2018****(5yrs 7mths 25days COE left)****Mileage****42,000 km (9.7k /yr)****Manufactured** ⓘ**2018****Road Tax** ⓘ**\$682 /yr****Transmission****Auto****Dereg Value** ⓘ**\$23,573 as of today (change)****Fuel Type****Petrol-Electric****COE** ⓘ**\$32,900****OMV** ⓘ**\$17,823****Engine Cap****1,496 cc****ARF** ⓘ**\$7,823****Curb Weight** ⓘ**1,080 kg****Power****101.0 kW (135 bhp)****Type of Vehicle****Hatchback****No. of Owners** ⓘ**1**