

ASS. REC. BY:

REF:

MSG/ 23006018/169

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMZ 7154C Yr Regn: 08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Got BT

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Sean Chun Yui, Chyi
Blk 460B Bukit Batok West Ave 9
#04-43
Singapore 652460

Vehicle No : SMZ 7154 C
Make : Kia Cerator
Year : 2019

Not Authored
1/1 Page &
Money After Rain
Today

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear n/s door
1 pc	Rear n/s door inner trim board
1 pc	Rear n/s door glass regulator
1 pc	Rear n/s door glass regulator motor
1 pc	Rear n/s door inner lock
1 pc	Rear n/s door rubber
1 pc	Rear fender
1 pc	Rear n/s fender air duct
1 pc	Rear n/s fender inner shield
1 pc	Rear n/s fender inner trim board
1 pc	Rear windscreen moulding
1 pc	Rear bumper
1 pc	Rear n/s bumper side retainer
1 pc	Rear n/s shock absorber
1 pc	Rear n/s wheel hub
1 pc	Rear axle assy
1 pc	N/S rocker panel garnish

R	\$1,385.00	✓
	\$587.00	?
	\$255.00	?
	\$405.00	?
	\$287.00	?
Dri	\$225.00	50% in
R	\$1,183.00	—
R	\$115.00	X
R	\$85.00	X
R	\$399.00	X
R	\$90.00	✓
R	\$688.00	X
R	\$85.00	X
	\$205.00	?
	\$389.00	?
R	\$1,049.00	X
	\$850.00	?
	\$8,282.00	
Less 10 %	\$828.20	
	\$7,453.80	

S. Nett Item

1 pc	Rear n/s tyre rim
1 pc	Rear n/s door edge protector
1 pc	Rear windscreen sealant
30 pcs	Rear bumper clip

Net	\$480.00	✓
R	\$120.00	40% in
R	\$30.00	✓
\$2.50	\$75.00	X
	\$705.00	

Labour Charges

Remove/renew the above parts including knocking, cutting & welding.

balance c/f	\$1,500.00	80%
	\$9,658.80	

MZ 7154 C

balance b/f \$9,658.80

Labour Charges

To putty & spray paint on accident affected portion.	\$1,200.00	800
Check/reconnect wiring.	\$60.00	200
To spray anti rust on accident affected portion.	\$180.00	600
Remove/renew rear windscreen to facilitate repair.	\$120.00	✓
Remove/refit roof lining to facilitate repair.	\$180.00	1000
Remove/refit fuel tank to facilitate repair.	\$120.00	600
Remove/renew rear undercarriages.	\$480.00	7
Check and realign wheel alignment	\$80.00	600
Remove/renew rear n/s door mechanism to new door	\$120.00	600
Total	<u>\$12,198.80</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/06/2023 14:22 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	12/06/2023 17:48 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BUKIT BATOK AVE 6, AVE 3
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMZ7154C

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SEAN CHUN YUIN CHYI
NRIC No	S7700232D
Email Address	MASSIVETRD@GMAIL.COM
Mobile Phone No	(Phone) +65-91053307
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMHCSNA00001492301

DRIVER

Name of Driver	SEAN CHUN YUIN CHYI
NRIC No	S7700232D
Date Of Birth	05/01/1977
Occupation	Outdoor

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Bukit Batok Ave 6, Ave 3

[Signature]

13/6/2023

Witnessed by Reporting Centre Personnel

Sketch Plan

