

ASS. REC. BY:

REF:

MSG/ 23008 018/16943

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 Got BT

21/6/11 Pm @ 57001 Centre Used \$ 6498.80, 53%

Date/Time, File Pass to?

1) 22/6/11 Pm

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 5700

MER-TP

5700

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Veh No:

PM 71540 Yr Regn: 08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Cerato C.C. 1391

Colour

M.P. White A/C: Insured / Std / NI / NA

Sp. Reading

128246 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAF5416MK 5051160

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

7 mm

Rear

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

12/6/23

D.O.I.

14/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.