

TP

SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera



User ID

Section A - Accident Details

Registration Number	SHB1999G
Case Reference Number	TAX/06/23/2028
Registration Date	29/12/21
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	GOH AH LENG
Type of Accident	Head To Side
Accident Date and Time	12/6/23 10:10 AM
Accident Reported Date and Time	12/6/23 3:58 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118638
Special Instruction to ARC, if any	LEFT REAR
Prepared Date and Time	12/6/23 5:05 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$900.00	\$0.00
Total Spray Cost	\$658.00	\$0.00
Total Spare Part Cost	\$2,199.62	\$0.00
Total Other Cost	\$1,000.00	\$0.00
TOTAL COST	\$4,757.62	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	02 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	12/06/2023 5:17 PM	
Signature		

Remarks

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number
Quotation Date		Invoice Date
Invoice Amount		Prepared Date

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[illegible]