

REF: CS1/LAW23006067/Dny3

Special Instruction:

ASSIGNMENT (Office)

From (Person): MUHAMMAD HAZDI of KELVIN CHIA Date/Time: 15/06/2023  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

LS: \$ 6200 / 12 DAYS

*Third Parties:*

Claimant:

Surveyor:

Workshop: EQUATOR

~~EQUALITY~~  
BROTHERHOOD

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: FBK 632U Insured: SLG 8603D

at Workshop m/s EQUATOR BROTHERHOOD

Tel:

of 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800

Policy No: \_\_\_\_\_ Claim No: SS/2021000304

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_  
(Client's Record) \_\_\_\_\_ D.O.A. 17/01/2020

H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: 17/07/23 Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_\_ days (Red \$ \_\_\_\_\_ / \_\_\_\_\_ %; Original 7 \_\_\_\_\_ days)

Date/Time: 17/07/23 Submit Final Fig 3700, 6 days (Red \$ 5465 / 59 %; Original 12 days)

[illegible]

**Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)**

**Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)**

**Para(3) : Nett Value**

Market Value :

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

*Fee Charged:*

Basic &amp; Add

Transport

## Photos

Others

Total

Date: \_\_\_\_\_

1) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_