



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23006068/Unp3m4	
			Date: 03/07/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLM 7222U	Veh. Inspected	GBG 8622S
	Policy No.	D23MTPV01004827	Coverage (\$)	0.00
	Claim No.	CMTD2302366/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	15/06/2023
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV350 (A)	c.c	2488
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JN1MC2E26Z0008800	Colour	SILVER
	Odometer	177146 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	AUSTONE	3 mm
	L/H Front Tyre	195 R15	AUSTONE	3 mm
	R/H Rear Tyre	195 R15	AUSTONE	5 mm
	L/H Rear Tyre	195 R15	AUSTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/06/2023	Inspection Date	16/06/2023
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	