



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD	Ref: NS/INC23006082/Tvp3m4
75 BRAS BASAH ROAD	Date: 30-06-2023
INCOME CENTRESINGAPORE 189557	Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNF 6496R	Veh. Inspected	SHC 7044S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1227469-002	Excess (\$)	0.00
Assign From		Assign Date	14/06/2023

2. Vehicle Particulars & Condition

Make & Model	BYD E6	c.c	0
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	LC0CE4DC8N0486807	Colour	YELLOW
Odometer	13214	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	WEST LAKE	6 mm
L/H Front Tyre	215/55 R17	WEST LAKE	6 mm
R/H Rear Tyre	215/55 R17	WEST LAKE	6 mm
L/H Rear Tyre	215/55 R17	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/06/2023	Inspection Date	14/06/2023
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------