

(08/11 /13) wef

ASS. REC. BY: / Taufikh

REF:

NS/ INC 23006082/Tvp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SNF 6496R

Policy No. _____

Claims No. MT/1227469-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: Ms Loke Vehicle: IN / OUT

Veh No: SHC 70449 Yr Regn: 2023, Apr

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BYD E6 c.c. -

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 13214 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LL0CE4DC8N*0486807

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wintake

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/6/2023 D.O.I. 14/6/23

Survey held at Carport Cozy

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/6/23	Taufikh confirmed final fig \$2951.40 (red 1230.40, 29%)

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) 28/6/23-typist

Report Format : TP

Lump Sum / I.B.I: (\$ 2951.40)

Days Of Repair: 2

Resurvey No. of Trip: _____

- Add Fee:
- : Site Insp (\$ _____)
 - : Interview (\$ _____)
 - : Tech. Invs (\$ _____)
 - : Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC7044S

Make : BYD

Model : NEW E6

Date: 14/06/2023

Insurance: INCOME

MVA MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER UPPER BODY			\$ 2,016.00
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER LOWER BODY			\$ 528.75
2	REAR BUMPER BRACKET LF RF		\$ 29.25	\$ 58.50
1	REAR BUMPER BRACKET LR RR		\$ 65.25	\$ 65.25
1	REAR BUMPER BEAM			\$ 661.50
SUB TOTAL				\$ 3,417.25
LESS 20% DISCOUNTED TOTAL				\$ 683.45
DISCOUNTED TOTAL				\$ 2,733.80
	REAR BUMPER RUBBER MAT			\$ 50.00
				\$ 50.00
	Labour Charge			
	PANEL BEATING			\$ 800.00
	SPRAY PAINTING CHARGE			\$ 500.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 80.00
	TOTAL LABOUR			\$ 1,380.00
	ESTIMATE TOTAL			\$ 4,163.80

Taufik 9749 5749
 up: 14/6/23 @ 4pm
 p/p Resny before paint
 2 days
 Taufik @ Kuantan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5900188


JC NO305557724

CUSTOMER CITYCAB PTE LTD 7010070 383 SIN MING DRIVE Singapore SINGAPORE 575717 65551188 (O) (P) SCOUNT CARD NO.	REGN NO: SHC7044S	MILEAGE
	MAKE: BYD	FUEL E.....1/2.....F
	MODEL: NEW E6	DATE/TIME IN: 14.06.2023 10:40
	YR OF MANU: 27.04.2023	TARGET DATE
	CHASSIS CODE: LCOCE4DC8N0486807	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 14.06.2023
NATURE: 3P 13.06.2023

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHC7044S** **YY**

Vehicle No.: **SHC7044S**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard