

(08/11/13)

well

ASS. REC. BY:

REF:

CS/SMR 23006085/Rvg3

9353

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 5538G

at Workshop m/s CYCLE & CARRIAGE

of PAMON GARDEN

Insured: SHC 4946J SMR

Policy No.

Claims No. TAX/05/23/2067

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

62K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIM IT - 42K

Veh No:

SKW 5538G

Yr Regn:

2018 / SH

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI ATTRAQ 1.2 CVT c.c 1193

Colour:

RED

A/C: Insured / Std / NI / NA

Sp. Reading

138638

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MMBSTA13A3H 003490

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/05/23

D.O.I.

26/06/23

Survey held at

CYCLE (PG)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

14/7/23 Final fig \$11,912 confirmed by email (Red 3462, 22%)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 14/7/23-typist

Days Of Repair: 9

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format : TP

Lump Sum / I.B.I: (\$ 11,912)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

) S + RS SI

) Photos

) Others

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/06/2023 14:13 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	23/05/2023 07:25 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	TOWARDS TUAS
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW5538G
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN CHUN HAN
NRIC No	S7805935D
Email Address	junhan78@yahoo.com
Mobile Phone No	(Phone) +65-96882969
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1300

INSURANCE COMPANY

Name of Insurance Company	Great Eastern General Insurance Limited
Policy Number / Cover Note Number	V5006613

DRIVER

Name of Driver	TAN CHUN HAN
NRIC No	S7805935D
Date Of Birth	02/03/1978
Occupation	Indoor

Date Of Driving Pass	08/08/1978
Driving experience	44 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96882969
Alt. Phone Number	-
Email Address	junhan78@yahoo.com
Address	BLK211A PUNGGOL WALK #12-623
Address complement	-
Postcode	821211
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC4946J
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	JAHAYA BIN AMAD
NRIC No	S7043378H

Contact Number	(Phone) +65-98379443
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers or the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or forms to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared/disclosed:
 - (i) to all insurers and/or any other third parties that exist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

[Signature]
Policyholder / Insured
Date: 27 May 2021

[Signature]
Authorised Driver
Date: 27 May 2021

[Signature]
Witness
Date: 27 May 2021

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23 May 2015, 7.25am, I was on my way to work on Pan Island Expressway (P.E.) towards Tuen I was on the extreme right lane (Lane 1). The traffic was moderately heavy.

The car in front of me slowed down and a truck in emergency stop. I stopped behind the car. However, the ^{truck} car behind me (SHC 41465) did not stop in time. The truck banged into my car behind.

I wore down out of my car and we went over to the side to get emergency to handling police personnel. The driver, Tachya asked me to go to make a report and make an insurance claim for my company.

We left the site accident site there.

DECLARATION

(Sign and date) I declare the foregoing particulars are true to my knowledge.

TS

TS



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHUN HAN (CHEN JUNHAN)	Cust No/Name /TAN CHUN HAN (CHEN JUNHAN)
100 Faber Terrace	Reg No/Reg Date SKW5538G / 26/09/201
Singapore 129600	Date In/Mileage / 0
Contact No Mobile: 96882969	Chassis No MMESTA13AJH003490
	Engine No 3A92UHH3426
	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	26/06/2023/ 16:50		1015/ Vikneswaran Naidu A	34769			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER, BOOTLID, RR BODY KIT,RR END PANEL REPAIR BOTH REAR FENDER								3200 3840.00
E PNT98000 SPRAY RR BUMPER, BOOTLID, RR BODYKIT, RR END PANEL, RR BOTH RH & LH FENDER,								2200 3800.00
E PNT88000 REMOVE ADN REFIT SENSOR								100.00
E PNT88000 REMOVE AND TRASNFER TRIM AND BONNET MECHANICSM								280.00
E PNT88000 REMOVE AND REFIT FLOOR COMPARTMENT								180 280.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								280.00
A 10028901 CHECK WIRING AND ELECTRICAL								100.00
M SUNDRY ANTI RUST PROOFING								100 150.00
M SUNDRY SUPPLY BODY PNL SEALANT								100 150.00
M SUNDRY SUPPLY CNC EMBLEM								80.00
M SUNDRY SUPPLY NUMBER PLATE								120.00
M SUNDRY SUNDRIES								20 100.00
M FACE,RR BUMPER					1.00	1268.00	00.00	1268.00
M BRACKET,RR BUMPER,LH					1.00	34.00	00.00	34.00
M BRACKET,RR BUMPER,RH					1.00	34.00	00.00	34.00
M MARK,THREE-DIA					1.00	86.00	00.00	86.00
M MARK,ATTRAGE					1.00	26.00	00.00	26.00
M PANEL,RR END					1.00	440.00	00.00	440.00
M LAMP ASSY,COMB,RR LH					1.00	661.00	00.00	661.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722



mitsubishi
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN CHUN HAN (CHEN JUNHAN)	Cust No/Name	/TAN CHUN HAN (CHEN JUNHAN)
100 Faber Terrace	Reg No/Reg Date	SKW5538G / 26/09/201
Singapore 129600	Date In/Mileage	/ 0
Contact No Mobile: 96882969	Chassis No	MMESTA13AJH003490
	Engine No	3A92UHH3426
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	26/06/2023/ 16:50		1015/ Vikneswaran Naidu A	34769

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LAMP ASSY, COMB, RR RH <i>1. xan</i>	1.00	661.00	00.00	661.00
M PANEL, TRUNK LID <i>1. xan</i>	1.00	835.00	00.00	835.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SURVEYOR NAME: *Rahul - Hp 90010068*
 SURVEYOR SIGNATURE: *[Signature]*
 DATE: *26/06/23 @ 1630*
 REMARKS: *8 days + 1 = 9 days*
Resurvey before paint

Confirm & accepted by

	Nett	12,825.00
8% GST on	12825.00	1026.00
Total Payable		13,851.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : RASUL LKK
Claim : TP FIRST CAPITAL
DOA : 23.05.2023
Emailed : 13.07.2023
Date Survey : 26.06.2023

VEHICLE NO : SKW5538G

MODEL : MIT/ATTRAGE

WIP : 34769

Material	:	\$	<u>4,082.00</u>
Labour	:	\$	<u>7,830.00</u>
Sub-Total	:	\$	<u>11,912.00</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>11,912.00</u>
GST 8%	:	\$	<u>952.96</u>
Grand Total	:	\$	<u>12,864.96</u>
Finalise By/Date	:	<u>VIC/11.07.2023</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 9 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 9

☒ TP claim FIRST CAPITAL

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHUN HAN (CHEN JUNHAN) 100 Faber Terrace Singapore 129600 Contact No Mobile: 96882969 26/06/2023	Cust No/Name /TAN CHUN HAN (CHEN JUNHAN) Reg No/Reg Date SKW5538G / 26/09/2018 Date In/Mileage 26/06/2023/ 138638 Chassis/Package MMESTA13AJH00349C /# Engine No 3A92UHH3426 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	13/07/2023/ 18:57	VIC	1015/ Vikneswaran Naidu A	34769			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3200.00
RENEW RR BUMPER, BOOTLID, RR BODY KIT & RR END PANEL								
E PNT98000								2200.00
SPRAY RR BUMPER, BOOTLID, RR BODYKIT & RR END PANEL								
E PNT88000								100.00
REMOVE & REFIT SENSOR								
E PNT88000								280.00
REMOVE AND TRANSFER TRIM AND BONNET MECHANISM								
E PNT88000								180.00
REMOVE AND REFIT FLOOR COMPARTMENT								
A 10028901								280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
A 10028901								100.00
CHECK WIRING AND ELECTRICAL								
M SUNDRY								100.00
ANTI RUST PROOFING								
M SUNDRY								100.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								80.00
SUPPLY CNC EMBLEM								
M SUNDRY								20.00
SUNDRIES								
Z TEXT								
TP CLAIM FIRST CAPITAL								
SURVEYOR: RASUL								
DOA: 23.05.2023								
09 REPAIR DAYS								
E PNT88000								640.00
ADDITIONAL JOB - REPAIR RH REAR FENDER								
E PNT98000								550.00
ADDITIONAL JOB - RESPRAY RH REAR FENDER								
X		FACE,RR BUMPER			1.00	1268.00	00.00	1268.00
X		BRACKET,RR BUMPER,LH			1.00	34.00	00.00	34.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 64739722



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHUN HAN (CHEN JUNHAN) 100 Faber Terrace Singapore 129600 Contact No Mobile: 96882969 26/06/2023	Cust No/Name /TAN CHUN HAN (CHEN JUNHAN) Reg No/Reg Date SKW5538G / 26/09/2018 Date In/Mileage 26/06/2023/ 138638 Chassis/Package MMBSTA13AJH00349C /# Engine No 3A92UHH3426 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	13/07/2023/ 18:57	VIC	1015/ Vikneswaran Naidu A	34769

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BRACKET,RR BUMPER,RH	1.00	34.00	00.00	34.00
X MARK,THREE-DIA	1.00	86.00	00.00	86.00
X MARK,ATTRAGE	1.00	26.00	00.00	26.00
X PANEL,RR END	1.00	440.00	00.00	440.00
X PANEL,TRUNK LID	1.00	835.00	00.00	835.00
X FRONT, REAR & SPOILER	1.00	1000.00	00.00	1000.00
X BUZZER,KEYLESS OPERATIO,RR	1.00	96.00	00.00	96.00
X COVER,RR VENTILATOR	1.00	50.00	00.00	50.00
X BOARD,TRUNK ROOM FLOOR	1.00	204.00	00.00	204.00
X CLIP,GEARSHIFT CONTROL LIN	3.00	3.00	00.00	9.00

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,082.00	Nett	11,912.00
Labour	7,530.00	8% GST on	952.96
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	12,864.96
Diagnostics Job	0.00		
Sundry/Others	300.00		
Total(w/o GST)	11,912.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

(ADDITIONAL)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Buzzer	? / SUPP			
2	Air Duct	? / SUPP			
3	Floor Board Rear	? / SUPP			
4	Screw.	? / SUPP			
5	Repair Rear Right Fender \$640	? / SUPP			
6	Spray Rear Right Fender \$550	? / SUPP			
7		? / SUPP			
8	At Add 1 Repair Days.	? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	30/6/23	[Signature]
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Mit / Affrage.

SURVEYOR: Rasul



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 64739722



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHUN HAN (CHEN JUNHAN) 100 Faber Terrace Singapore 129600 Contact No Mobile: 96882969 26/06/2023	Cust No/Name /TAN CHUN HAN (CHEN JUNHAN) Reg No/Reg Date SKW5538G / 26/09/2018 Date In/Mileage 26/06/2023/ 138638 Chassis/Package MMBSTA13AJH00349C /# Engine No 3A92UHH3426 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	13/07/2023/ 18:56	VIC	1015/ Vikneswaran Naidu A	34769

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 ADDITIONAL JOB - REPAIR RH REAR FENDER				640.00
E PNT98000 ADDITIONAL JOB - RESPRAY RH REAR FENDER				550.00
X FRONT, REAR & SPOILER <i>cm</i>	1.00	1000.00	00.00	1000.00
X BUZZER,KEYLESS OPERATIO,RR <i>cm</i>	1.00	96.00	00.00	96.00
X COVER,RR VENTILATOR <i>cm</i>	1.00	50.00	00.00	50.00
X BOARD,TRUNK ROOM FLOOR <i>cm</i>	1.00	204.00	00.00	204.00
X CLIP,GEARSHIFT CONTROL LIN <i>cm</i>	3.00	3.00	00.00	9.00

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	1,359.00	Nett	2,549.00
Labour	1,190.00	8% GST on	2549.00
Standard Menu	0.00		203.92
Specialist Job	0.00	Total Payable	2,752.92
Diagnostics Job	0.00		
Sundry/Others	0.00		
Total(w/o GST)	2,549.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.