

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Income (Sum)

Date: 13.04.2023
Time: 08:53:18
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305551025
REGN NO : SHC1242B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 10.07.2019
DATE/TIME IN : 12.04.2023 15:25
ACCIDENT DATE : 12.04.2023

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2292-G COVER-FR BUMPER# 1 481.10 20.00 384.88 ~~384.88~~ (RA ✓)
0002 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60 XIVV

SUB-TOTAL : 402.48

JOB NATURE

0000 PB PANEL BEATING 400.00 350
0001 SP SPRAYPAINT CHARGE 300.00 250

SUB-TOTAL : 700.00

TOTAL : 1,102.48

MVA NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE:

T = 984.88
Wbp = 196.47
= 787.40

≈ 800 X

2 dys L/S
13/4/23

S/11km

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: