

(08/11/13) wef

ASS. REC. BY: AM

REF:

CC4/11123006133/Ry3

6204

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FBK 62643at Workshop m/s HKLof BANKIT MERAHInsured: 111

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: 9k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBK 62643Yr Regn: 2015/ NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda CR400SF Manual c.c. 399Colour BLUE

A/C: Insured / Std / NI / NA

Sp. Reading -

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NC421603944Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Mod: NII / S/Rim / STD A/Rim or _____Tyre Size: F: 120/60ZR7R: 160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 4

mm

R/Bal. 5

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. 10/06/23D.O.I. 16/06/23Survey held at HKL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR & O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 7K

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

) S + RS. SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	670H
Vehicle No.:	FBK6264J
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jun 2023
Vehicle Make:	HONDA
Vehicle Model:	CB400SF MANUAL
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	NC42E1203946
Chassis No.:	NC421603944
Maximum Power Output:	-
Open Market Value:	\$7,610.00
Original Registration Date:	19 Nov 2015
First Registration Date:	19 Nov 2015
Transfer Count:	5
Actual ARF Paid:	\$1,142.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	18 Nov 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,912.00
COE Rebate Amount:	\$1,440.00
Total Rebate Amount:	\$1,440.00

The information contained herein is correct as at 20 Jun 2023

OK



Search SGBikemart



Brand

Honda

Model

Honda CB400X

Type of Vehicle

Sport Tourers

No. of owners

-

Mileage

-

Listing Type

Paid Ad

Engine Capacity

399cc

Classification

Class 2A

Registration Date

23/11/2015

COE Expiry Date

22/11/2025

(2yrs 5mths 2days COE left)



Contacts