SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 9. Information provided mast by as distinct and second as positive policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurance Association of Singapore (GIA) for archiving the insurance Association of Singapore (GIA) for archi and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| 17/05/2023 12:02 (SGT) |
|--|
| OF OWN VEHICLE |
| SMF4251E |
| |
| TAN YONG SOON |
| |
| Elantra - Private use No - Claiming third party Private car Auto |
| |

Income Insurance Limited

5119736805-02

TAN YONG SOON

Outdoor

Occupation Accident report SS36235I0002

INSURANCE COMPANY

DRIVER

NRIC No Date Of Birth

Name of Driver

Name of Insurance Company

Policy Number / Cover Note Number

| Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver | 28/03/1985 38 YEARS AND 2 MONTHS Male (Phone) |
|--|---|
| GENERAL INFORMATION OF THE ACCIDENT | |
| Type of Accident Weather Conditions Road Surface OTHER INFORMATION | Collision - Head to Rear Clear Dry |
| Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement | No 2 No - Yes 1 No |
| DETAILS OF POLICE ACTION | |
| Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom? | No No - |
| CIRCUMSTANCES OF ACCIDENT | |
| REFER TO ACCIDENT STATEMENT ATTACHED. ON 17/05/2023 AT ABOUT 1202PM, I DROVE MY VEHICLE SMF THE ZEBRA CORSSING, SUDDENLY THIS VEHICLE (GBC402 VEHICLE. AFTER THE ACCIDENT, WE ALIGHTED FROM OUR VEHICLE DRIVER, THE DRIVER DID NOT TAKE MY PARTICUALRS, ON | 3T) COLLIDED ONTO THE REAR PORTION OF MY , I TOOK PHOTOGRAPHS , PARTICULARS OF THE |
| ATTACHMENT(S) | |
| | |

Are accident photos available for attachment? Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC4023T Vehicle Manufacturer -

| Vehicle Model | - |
|---|----------------------|
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | MR LEW |
| Contact Number | (Phone) +65-82221676 |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Traffic Police Department for investigation.

- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agen (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)


Sketch Plan



vJun2022

| | 2023 at about 1 E along Ocean the Jebra (ro 4023T) colling. | | | | |
|----------------|---|----------------|---------------|-------------------------------|-----|
| l to driver | the accident, ok pholographs, diel not take at numbers. | particulars of | of the chiver | venicles, the exchanged | |
| Contra | of Mumbers. | | | 1 700 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | 9 | | | | |
| | | | | | |
| | | | <i>f</i>) | | |
| | | | | • | |
| uration | | | | | |
| | articulars are true in every resp | pect. | | | M/X |













JP Ca 23 2501 TSM

德松 嚤 哆 服 务 TECK SIANG MOTOR SERVICE

Specialisd in Motor Vechicles,
Insurance Claim
Spray Painting, Panel Beating
& Welding Etc.

Reg 306747/00J Blk. 5034 Ang Mo Kio Industrial Park 2 Unit # 01-331, Singapore 569537 Tel. 64833 445 专修理汽车引擎, 喷漆打焊车身 代辦保险及 保险赔偿买卖旧车等

29 May 2023

Owner: Tan Yong Soon

COST OF REPAIRS TOSMF 4251 E HYUNDAI ELANTRA

| | DESCRIPTION | AM | OUNT (S\$) |
|---|---------------------------------------|----|------------|
| 1 | Lump Sum Repair as per recommendation | \$ | 6,300.00 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | \$ | 6,300.00 |

INVOICE

Invoice No.:

CL/230293

Tan Yong Soon

C/o: Teck Siang Motor Service

Blk 5034 Ang Mo Kio Ind Park 2

#01-331 Singapore 569537

Ref No.:

TSM/05/2301/TP

Date:

29 May 2023

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

SURVEY INSPECTION FOR VEHICLE NO.

SMF 4251 E

- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
 (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

S\$ 597.00

E & O. E

Notes / Payment method:

All cheque payment should be "Crossed" and made payable to "CLAPPRAISER PTE LTD"

Bank Transfer -

Account Name: C L APPRAISER PTE LTD

Account Number: 588041152001

Bank: OCBC

We shall be grateful if you could forward our payment at your early convenience.

CL Appraiser Pte Ltd

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Rea No: 201000228E

VEHICLE INSPECTION REPORT

To: Tan Yong Soon

Date

: 29 May 2023

C/o: Teck Siang Motor Service

Our ref

: TSM/05/2301/TP

Blk 5034 Ang Mo Kio Ind Park 2 #01-331 Singapore 569537

Accident Date

: 17 May 2023

Type of Survey : Third Party

Inspection Date

: 22 May 2023

Repairer Name

: Teck Siang Motor Service

Blk 5034 Ang Mo Kio Ind Park 2

#01-331 Singapore 569537

PARTICULARS OF VEHICLE

Registration No : SMF 4251 E

Year / Capacity :

2018 / 1591 cc

Make / Model

: Hyundai Elantra

Colour

White

4

Chassis No

: KMHD841CMJU767367

Mileage

201328

Engine No

: G4FGJU277131

CONDITION OF TYRES

| | | Make | Size | Thread Balance | Rim |
|----------------|-----|----------|------------|----------------|-------|
| Front Nearside | i i | Michelin | 195/65 R15 | 5 mm | Sport |
| Front Offside | 3 | Michelin | 195/65 R15 | 5 mm | Sport |
| Rear Nearside | : | Michelin | 195/65 R15 | 5 mm | Sport |
| Rear Offside | 2 | Michelin | 195/65 R15 | 5 mm | Sport |

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion. (Details refer to the photographs attached)

Enclosed number of photographs:

97

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$6,300.00 on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

Page 1



Vehicle Registration No.: SMF 4251 E

Our Ref No.:

TSM/05/2301/TP

| Qty | Description | Conditions | Repairer's | Revised |
|-----|--|------------|----------------|----------------|
| | | | Estimate | Amount |
| | SPARE PARTS - LIST ITEMS | | | |
| 1 | Rear boot lid | Damage | \$ 1,782.00 | \$ 1,782.00 |
| 2 | Rear boot hinges | Intact | \$ 275.60 | |
| 1 | Rear boot o/s lamp | Damage | \$ 362.50 | \$ 362.50 |
| 1 | Rear boot lock | Damage | \$ 250.80 | \$ 250.80 |
| 1 | Rear boot logo | Necessary | \$ 97.80 | \$ 97.80 |
| 1 | Rear boot "ELANTRA" emblem | Necessary | \$ 90.90 | \$ 90.90 |
| 1 | Rear boot "S" emblem | Necessary | \$ 88.90 | \$ 88.90 |
| 1 | Rear end panel | Damage | \$ 557.50 | \$ 557.50 |
| 1 | Rear end panel inner garnish | Damage | \$ 299.30 | \$ 299.30 |
| 1 | Rear smart keyless sensor | Damage | \$ 217.80 | \$ 217.80 |
| 1 | Rear bumper | Damage | \$ 500.20 | \$ 500.20 |
| 2 | Rear bumper top brackets | Damage | \$ 131.60 | \$ 131.60 |
| 1 | Rear bumper lower diffuser | Damage | \$ 432.00 | \$ 432.00 |
| 1 | Rear bumper reflector | Damage | \$ 99.80 | \$ 99.80 |
| 1 | Rear bumper reinforcement | Damage | \$ 455.80 | \$ 455.80 |
| 2 | Rear bumper reinforcement stays | Damage | \$ 401.60 | \$ 401.60 |
| 3 | Rear bumper reinforcement brackets | Damage | \$ 434.70 | \$ 434.70 |
| 2 | Rear bumper side retainers | Necessary | \$ 135.60 | \$ 135.60 |
| | • | • | \$ 6,614.40 | \$ 6,338.80 |
| | | Less 10% | \$ 661.44 | \$ 633.88 |
| | Total Cost - List Items | | \$ 5,952.96 | \$ 5,704.92 |
| | CDECLAL NEWSTANDARD | | | |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | Rear bumper clip (1 set) | Necessary | \$ 50.00 | \$ 50.00 |
| 1 | Rear reverse sensor (1 set) | Damage | \$ 350.00 | \$ 350.00 |
| | Total Cost - Special Nett items | | \$ 400.00 | \$ 400.00 |

Total cost of parts

| 2 | 6,352.96 | \$ 6,104.92 |
|---|----------|----------------|



Vehicle Registration No.: SMF 4251 E

Our Ref No.:

TSM/05/2301/TP

| S/No | Description | | epairer's Estimate | Revised Amount |
|------|---|----|-----------------------|-------------------|
| | Total cost of parts c/f | \$ | 6,352.96 | \$ 6,104.92 |
| | <u>LABOUR</u> | | | |
| 1 | To remove, refit, replaced damaged lamps and check up rear electrical wiring | \$ | 80.00 | \$ 50.00 |
| 2 | To remove and refit inner garnishes, inner trim to assist repair. | \$ | 120.00 | \$ 80.00 |
| 3 | To remove and refit rear reverse sensor. | \$ | 120.00 | \$ 80.00 |
| 4 | To transfer boot lid mechanism and wiring assembly to assist repair. | \$ | 80.00 | \$ 80.00 |
| 5 | To apply undercoating on repaired and replaced panel. | \$ | 120.00 | \$ 90.00 |
| 6 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident. | \$ | 1,080.00 | \$ 750.00 |
| 7 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. | \$ | 1,000.00 | \$ 660.00 |
| | GRAND TOTAL | \$ | 8,952.96 | \$ 7,894.92 |



Vehicle Registration No.: SMF 4251 E

Our Ref No.:

TSM/05/2301/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 6,300.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer


The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser

























































































































































































Your Ref : GBC 4023T Fax : $6538\ 3708$ Our Ref : SMF 4251E/TSM/jp/cq Tel : $3152\ 0993$

Date : 19 May 2023 Email : accident@kscgp.com

LONPAC INSURANCE BERHAD

BY EMAIL ONLY

DATE OF ACCIDENT: 17 MAY 2023 NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of SMF 4251E to notify you of a road traffic accident on 17 May 2023 at about 12:02 p.m. along Ocean Way, involving our client's vehicle registration number SMF 4251E and vehicle registration number **GBC 4023T**, which was insured by you at the material time. A copy of the Singapore accident statement is enclosed herewith.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

CQ

Enc.

Your Ref : GBC 4023T Fax : $6538\ 3708$ Our Ref : SMF 4251E/TSM/jp/cq Tel : $3152\ 0993$

Date : 19 May 2023 Email : accident@kscgp.com

LONPAC INSURANCE BERHAD

BY EMAIL ONLY

DATE OF ACCIDENT: 17 MAY 2023

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

| S/no. | Name of Surveyor | Company Name |
|-------|------------------|----------------------------|
| 1. | Dave Chang | Sincere Appraisal Services |
| 2. | Lee Kok Weng | Lee Automobile Services |
| 3. | Alan Cheong | CL Appraisal Pte Ltd |
| 4. | Andrew Aw | I-Spex Services |

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Teck Siang Motor Service

Block 5034 Ang Mo Kio Industrial Park 2

#01-331

Singapore 569537

Contact Person/Tel : Jordan Goh / Tel: 9006 0235

Yours faithfully,

f CQ

Your Ref $: GBC \ 4023T$

Our Ref : SMF 4251E/TSM/jp/cq

Date : 19 May 2023

Acknowledgement

| Thi | s is to confirm that I [Su | | | | | |
|-----|--|------------------------|------------------|--|--|--|
| (a) | Pre- Repair Survey/Inspection on | [Date] at | [Time]. | | | |
| | Name and signature of Appointed Surveyor Company Stamp | Witnessed by: Date: | | | | |
| (b) | Pre- Repair Survey/Inspection (during dismant | ling) on | [Date] at[Time]. | | | |
| | Name and signature of Appointed Surveyor Company Stamp | Witnessed by: Date: | | | | |
| (c) | Re-inspection of new replacement part (part by part) on [Date] at[Time]. | | | | | |
| | Name and signature of Appointed Surveyor Company Stamp | Witnessed by: Date: | | | | |
| (d) | Post – Repair Survey/Inspection on | [Date] at | [Time]. | | | |
| | Name and signature of Appointed Surveyor Company Stamp | Witnessed by: Date: | | | | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 18/05/2023 12:13 (SGT) Reported by **Actual Driver** Date of Accident 17/05/2023 12:00 (SGT) Exact Location of Accident Singapore Additional Location Information OCEAN DRIVE SENTOSA Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **GBC4023T**

INSURED/POLICYHOLDER

Is company? Yes

Name Of Registered Owner S & D MULTI SERVICES

VEHICLE PARTICULARS

Manufacturer Nissan Model Nv200 Variant

Vehicle Category Commercial vehicle

Transmission Manual 1461

INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd Policy Number / Cover Note Number Z22VC05013533

DRIVER

Name of Driver **LEW KIAN HUI** NRIC No. S8855676C

Address APT BLK 512 BEDOK NORTH AVENUE 2

Address complement # 07-301 Postcode 460512 Does Driver Own Other Vehicles?

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear

| Weather Conditions | Clear |
|--|-------------|
| OTHER INFORMATION | |
| Was any foreign vehicle involved in the accident? Was anybody injured in the Accident? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement | No No Yes 1 |
| CIRCUMSTANCES OF ACCIDENT | |

PLEASE REFER TO THE ATTACHED STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

| Vehicle Registration Number | SMF4251E |
|-----------------------------|-------------|
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Private car |
| Name of Driver | _ |
| Insurance Company Name | _ |

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Drive ocean

5/18/23, 10:33 AM Ocean Dr - Google Maps Google Maps Ocean Dr Google Street View See more dates Google Image capture: Apr 2019 W Singapore Sentosa Cove A- GBC 4023T B-SMF 4251E

https://www.google.com/maps/@1.2485958,103.8399851,3a,90y,223.37h,65.44l/data=!3m6!1e1!3m4!1sz9XQMeQsUmiaosQjGceV_A!2e0!7i16384!8i... 1/1



| .*.* | . : . : | |
|---|------------------|---|
| The Leading | | · · · · · · · · |
| on the above stated de | ate and time. | luce dinvina |
| alona ocean once somos | a. Vehicle B. W | as infront of. |
| mo. There was one vehice | le infront of v | rehicle B.he' |
| suddenly put on bruke | and turned to n | ight side. |
| upon sceing the vehicle | bruke, vehicle | B follow suit |
| and iam bruke as well. | I follow suit ar | nd my vehicle |
| fouched the year portion | of rehicle B | · it was just |
| a slight touch only. A | to severe damas | ges to both |
| vehicles. | | 0 |
| | | |
| | | |
| | • | |
| | | · · · · · · · · · · · · · · · · · · · |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Declaration | | |
| I/We declare the foregoing particulars are true in every resp | pect. | |
| SE UEN | | Λ |
| Q(53435145W)C | | dinimal islasts |
| | | |
| Policyholder's Signature / Date & Time Actual Driver's Si | 18/5/2023 | Witnessed by Reporting Centre Person (Name as in NRIC/ID card) |

v.km2022 .


























Enquire Vehicle Owner Details (As At 17 May 2023 / 12:02:00)

Vehicle Owner Details

Owner ID Type: Owner ID:

Business 53435145W

Owner Name: Registered Address Type:

S & D MULTI SERVICES HDB / HUDC

Registered Block/House No.: Registered Street Name:

2 YISHUN INDUSTRIAL STREET 1

Registered Unit No.: Registered Building Name:

08 - 10 NORTH POINT BIZHUB

Registered Postal Code:

768159

Vehicle Insurance Details

Vehicle No.: Make Description/Model:

GBC4023T NISSAN / NV200 1.5L MT ABS AIRBAG 2WD

6DR

Insurance Company Name:

LONPAC INSURANCE BHD

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

GBC4023T

Date of Accident

17/05/2023 苗

Reset

% RESULT & RECEIPT

TP Insurer Enquiry Insurance Lonpac Insurance Bhd Period of Insurance 23/09/2022 - 22/09/2023 Requested By KSCGP01 (KSCGP JURIS LLP) Requested Date 19/05/2023 09:29

Payment details

Request Amount: **\$\$1.85** GST Amount: **\$\$0.15**

Total Amount Due (GST Inclusive): **\$\$2**

General Insurance Association

Records Management Centre GST Registration No: **M400017735**



380 Jalan Besar Road, #13-02/04 ARC380, Singapore 209000 (201401258N)

Receipt

Purchase Details:

Purchase Reference: 2023-0613-71BA-4D0S Seller Name: CRIF BizInsights

Purchase Date: 2023-06-13 15:25:54 Seller UEN / GST Reg No.: 201401258N

Purchased By: kfx2010

| Product | ID | Name | Price | Tax | Total |
|---------------------------------|-----------|----------------------|------------|----------|-------|
| Business Profile (BPF) Business | 53435145W | S & D MULTI SERVICES | 4.60 | 0.37 | 4.97 |
| | | | Grand Tota | I (S\$): | 4.97 |

This is a computer generated receipt. No signature is required.



Business Profile (BPFBIZ)

S & D MULTI SERVICES

Particulars

Name : S & D MULTI SERVICES

Registration Number / UEN : 53435145W

Incorporation / Registration Date : 12-06-2021

Name Effective Date : -

Commencement Date : 12-06-2021

Date of Last Renewal : -

Date of Expiry : 12-06-2024

Constitution : SOLE PROPRIETORSHIP

Registered Address : 2 YISHUN INDUSTRIAL STREET 1

#08-10 NORTH POINT BIZHUB

SINGAPORE 768159

Address Effective Date : -

Status : LIVE

Status Effective Date : 12-06-2021

Principal Activity Code (I) : 43210

Principal Activity Description (I) : ELECTRICAL WORKS

Principal Activity Code (II) : 41001

Principal Activity Description (II) : GENERAL CONTRACTORS (BUILDING CONSTRUCTION

INCLUDING MAJOR UPGRADING WORKS)

Former Name(s)

NIL

Date/Time Generated: 13-06-2023 15:25:54PM Page 1 of 2

Business Owner(s)

| No. | Name | ID | Nationality | Date of Appointment |
|-----|---|-----------------------------|-------------|------------------------|
| 1 | LEW KIAN HUI | S8855676C | MALAYSIAN | 12-06-2021 |
| | Address | Date of Change (Address) | | |
| | 512 BEDOK NORTH AVENUE 2 #07-301 KAKI BUKIT | 01-08-2022 | | |

Authorised Representative(s)

NIL

Nominee/Trustee(s)

NII

Withdrawn Personnel

NIL

Disclaimer

The information in this report is extracted by BizInsights from a database comprising information filed with the Accounting & Corporate Regulatory Authority (ACRA) on or before 11 June 2023 and presented using a business intelligence solution. The statements or ratios published by BizInsights are solely statements of opinion and not statements of fact or recommendations to purchase, hold, or sell any securities or make any other investment decisions. Subscribers should not rely on any such statements or ratios in making any investment decision. This report may not be reproduced in whole or in part in any form or manner. The report may contain information compiled from information which ACRA and BizInsights do not control and which has not been verified unless indicated in this report. Whilst every endeavor is made to ensure that the information provided is updated and correct, ACRA and BizInsights disclaim any liability for any damage or loss that may be caused as a result of any error or omission arising out of or in any way related to the contents of this report. Certain figures in the financial statements may have been adjusted for analytical classification purposes in accordance with established methodology and research processes.

 Date/Time Generated:
 13-06-2023 15:25:54PM
 Page 2 of 2