

Ass. By:

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Insured Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claim No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SK73299T Yr Regn: 2022, Oct

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MG ZS C.C. _____

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 13198 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LSTW74093M 2115591

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim, or

Tyre Size: F: 215/50R17

R: 215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 20/06/23

Survey held at Eurokars

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP Claim

COE Expiry

Estimate given during : Yes (✓)
1st Survey : No ()

MV :

PV :

Nett :

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos

Others

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Inve (\$ _____)

Report Formed: _____

Report Form / L.P. / C.C.

QUOTATION

EUROKARS EV PTE LTD

5 Ubi Close Singapore 408605

CODE: C0015
CUSTOMER: CHINA TAIPING INSURANCE (SINGAPORE) PTE
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

DOCUMENT DATE: 13 June 2023
POS OD: MU
PRINTED BY: JESS FRANCIS
SERVICE ADV:
CSP/OP CODE:
DEPT: 1
WIP NO.:
REF. NO.:
DATE IN: 02 June 2023
EXT. WTY:
MILEAGE: 0

CONTACT NO.:
MODEL: MG ZS EV UK
CHASSIS NO.: LSJW74093MZ115591
ENGINE NO.:
REG NO.: SKZ3299T
REGN DATE: 27 October 2022

DESCRIPTION:

Item	Description	Qty.	Unit Price	Disc.		Revise amount	Gross amount
				SGD	%	SGD	SGD
M10336751SPRP	FASCIA-FRT BUMPER UPR <i>Regis</i>	1.00	774.00	0		+	774.00
M90003375	CLIPS <i>Not nec</i>	2.00	1.00	0		+	2.00
M90003410	RIVETS <i>Not nec</i>	2.00	1.00	0		✓	2.00
M90004065	CLIPS <i>Not nec</i>	8.00	2.00	0		+	16.00
M10338991SPRP	COVER,TOW-HOOK <i>Not nec</i>	1.00	14.00	0		+	14.00
M10636556	BUMPER,LOWER <i>Not nec</i>	1.00	597.00	0		+	597.00
M91000181	CLIPS <i>Not nec</i>	4.00	2.00	0		+	8.00
M10582258	GRILLE,BUMPER-LOWER <i>Not nec</i>	1.00	299.00	0		+	299.00
M10582256	COVER CTR,GRILLE-RADAR	1.00	28.00	0		?	28.00
M10422032	PANEL,BUMPER-LOWER AIR DAM <i>Not nec</i>	1.00	197.00	0		+	197.00
M10014695	FINISHER RH,FRT FOG LAMP <i>Not nec</i>	1.00	198.00	0		+	198.00
M10014694	FINISHER LH,FRT FOG LAMP	1.00	198.00	0		+	198.00
M10560914	BRACKET RH,BUMPER-FRT	1.00	77.00	0		?	77.00
M90005040	GROMMET	4.00	3.00	0		?	12.00
M10560912	BRACKET LH,BUMPER-FRT	1.00	77.00	0		?	77.00
M10749654	GRILLE,RADIATOR <i>Not nec</i>	1.00	1,274.00	0		✓	1,274.00
M10349819SPRP	GRILLE,UP. RADIATOR <i>Not nec</i>	1.00	194.00	0		+	194.00
M10229023	SUPPORT,GRILLE UP. RADIATOR <i>Not nec</i>	1.00	137.00	0		+	137.00
M90005040	FASTENERS <i>Not nec</i>	4.00	3.00	0		✓	12.00
M10870712	BRACKET,GRILLE UP. RADIATOR	1.00	97.00	0		?	97.00
M91000181	GROMMET	6.00	2.00	0		?	12.00
M90003417	RIVETS <i>Not nec</i>	4.00	2.00	0		✓	8.00
M10984562	UNIT RH,HEADLAMP <i>Not nec</i>	1.00	1,680.00	0		+	1,680.00
M10984561 / M10	UNIT LH,HEADLAMP <i>Not nec</i>	1.00	1,680.00	0		+	1,680.00
M10596861	COVER,RADAR MIDDLE	1.00	18.00	0		?	18.00
M10928834/ M10	MODULE ASM FRT RADAR END	1.00	2,347.00	0		?	2,347.00
M10116429	CLIPS <i>Not nec</i>	3.00	9.00	0		✓	27.00
M10654675	BRACKET,FRT RADAR	1.00	24.00	0		?	24.00
M10950316	SOCKET,CHARGING	1.00	2,947.00	0		?	2,947.00
NOTES	TP CLAIM - CHINA +						
SUB	REPLACE FRT BUMPER. REPAIR BONNET.	1.00		0		600	1,320.00
SUB	SPRAY FRT BUMPER, BONNET, TOP-GRILLE.	1.00		0		630	1,575.00
SUB	SUPPLY NUMBER PLATE <i>Not nec</i>	1.00		0		-X	70.00

QUOTATION

EUROKARS EV PTE LTD

5 Ubi Close Singapore 408605

SUB	RECHARGE CAR BATTERY.	1.00	0	- ✓	165.00
SUB	CARRY OUT CHECKS TO REMOVE & REFIT CONNECTION POWER(HV OR 12V).	1.00	0	- X	165.00
SUB	ELECTRICAL CHECK FOR PROPER FUNCTION.	1.00	0	- 150	180.00
SUB	REPROGRAM AFTER THE ACCIDENT REPAIR WORKS.	1.00	0	- 180	200.00
SUB	SUNDRIES.	1.00	0	- X	50.00
EXC	Excess element of insurance repair to be paid by the insured party.	1.00	-	0	-

			Before GST	GST 8%	Total
Parts	12,956.00	Gross *	16,681.00	1,334.48	18,015.48
Surcharge	-	Less: Deposit**	-	-	-
Labour	3,725.00	Amount Due	16,681.00	1,334.48	18,015.48
Menus	-				

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date: _____

Customer signature _____

Authorised signature _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____