

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIED WORLD AS	SSURANCE COMPANY LTD	F	Ref:	CS/AWA23006159/Kqy3m4	
	(SINGAPORE BRA 60 ANSON ROAD : MAPLETREE ANSO	NCH) #08-01 (8th FLOOR) ONSINGAPORE 079914	Ε	Date:	10/07/2023	
			C	Code:	AWA	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	XD 4675X	Veh. Inspected		SNH 8596L	
	Policy No.	BVFCSB0006702318	Coverage (\$)		0.00	
	Claim No.	XD4675X/HLF	Excess (\$)		0.00	
	Assign From	HEW LEE FONG	Assign Date		19/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	AUDI A3 TFSI	c.c		1395	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	WAUZZZ8V5G1099644	Colour		METALLIC BLACK	
	Odometer	101099 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/50 ZR16	GREENTRAC		8 mm	
	L/H Front Tyre	205/50 ZR16	GREENTRAC		8 mm	
	R/H Rear Tyre	205/50 ZR16	GREENTRAC		8 mm	
	L/H Rear Tyre	205/50 ZR16	GREENTRAC		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	15/06/2023	Inspection Date		20/06/2023	
	Survey held at	OPTIMA WERKZ PTE LTD				
		10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					