



































INSPECTION REPORT FOR VEHICLE NO. CB85788

Our Surveyor	Third Party Surveyor
1st Inspection: Signature: <u>[Signature]</u> Name of Surveyor: <u>Jeff Yee</u> Contact No.: <u>917 650 7</u> Date & Time: <u>8/1/22</u>	1st Inspection: Signature: <u>[Signature]</u> Name of Surveyor: <u>Jeff Yee</u> Contact No.: <u>917 650 7</u> Date & Time: <u>8/1/2022 @ 9:20am</u>
2nd Inspection: Signature: <u>[Signature]</u> Name of Surveyor: <u>Jeff Yee</u> Contact No.: <u>910 353 22</u> Date & Time: <u>8/1/22</u>	2nd Inspection: Signature: <u>[Signature]</u> Name of Surveyor: <u>Jeff Yee</u> Contact No.: <u>917 650 7</u> Date & Time: <u>1:30pm - 8/1/2022</u>
3rd Inspection: Signature: _____ Name of Surveyor: _____ Contact No.: _____ Date & Time: _____	3rd Inspection: Signature: _____ Name of Surveyor: _____ Contact No.: _____ Date & Time: _____