

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC23006201/T	ncm4
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	12-07-2023 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SCJ 8679B	Veh. Ir	spected	SH 6343D
	Policy No.		Covera	age (\$)	0.00
	Claim No.	MT/1228013-002	Exces	s (\$)	0.00
	Assign From		Assign	n Date	19/06/2023
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I40	c.c		1685
	Engine No.	HIDDEN	Year o	f Reg.	2016
	Chassis No.	KMHLB41UMHU096479	Colou	r	BLUE
	Odometer	706581	Steerii	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	WEST	LAKE	6 mm
	L/H Front Tyre	205/60 R16	WEST	_AKE	6 mm
	R/H Rear Tyre	205/60 R16	WEST	_AKE	6 mm
	L/H Rear Tyre	205/60 R16	WEST	LAKE	6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	18/06/2023	Inspec	tion Date	19/06/2023
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD			
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				