

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH6598K

Make : Toyota

Model : Prius

Date: 08/06/2023

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT FENDER SUB ASSY RH			\$ 1,111.93
1	FRONT FENDER HYBRID EMBLEM RH			\$ 86.50
1	FRONT FENDER SHIELD RH			\$ 198.50
1	FRONT BUMPER COVER			\$ 586.18
1	FRONT BUMPER SIDE BRACKET RH			\$ 82.30
10	FRONT BUMPER CLIPS			\$ 22.00
1	HEADLAMP RH			\$ 2,735.28
1	FRT BUMPER FOG LAMP RH			\$ 920.00
1	FRT BUMPER TOWING COVER			\$ 28.38
1	WHEEL RIM FRT RH			\$ 1,570.55
	SUB TOTAL			\$ 7,341.62
	LESS 25%			\$ 1,835.41
	DISCOUNTED TOTAL			\$ 5,506.22
	Labour Charge			
	PANEL BEATING		525	\$ 1,100.00
	SPRAY PAINTING CHARGE		500	\$ 600.00
	CHECK LIGHTING		30	\$ 60.00
	TUFF KOTE		30	\$ 60.00
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 7,326.22

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 WP 9/6/23 @ 330pm
 02-03 days
 L/S Rising after repair
 Tanpin C/Maintenance

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Workshops205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

Date/Time: 09.06.2023 08:27 Page : 1

Team: ARC Repair TP(CLSO)1


JOB CARD Sales Order: 5899619

JC NO305557147

CUSTOMER	REGN NO.: SH 6598K	MILEAGE
MR/MS COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL E.....1/2.....
CUSTOMER NO. 7010045	MODEL PRIUS HYBRID(G4)08.	DATE/TIME IN 06.2023 14:05
ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717	YR OF MANU. 07.09.2017	TARGET DATE
TEL (R) 65508755 (O)	CHASSIS CODE JTDKB3FUX03563795	COMPLETION DATE/TIME
DISCOUNT CARD NO.		

JOB DESCRIPTIONAccident Date: 08.06.2023
NATURE: 3P 08.06.2023

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

re:

No.:

Vehicle No.: SH 6598K YY

Exit Pass

Vehicle No.: SH 6598K

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard