

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305557496
 REGN NO : SHA3308T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 30.04.2019
 DATE/TIME IN : 13.06.2023 08:00
 ACCIDENT DATE : 13.06.2023

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2538-G MIRROR ASSY-O/S RR VIEW R 1 1,391.70 20.00 1,113.36 *Car*

SUB-TOTAL : 1,113.36

JOB NATURE

0000 L PANEL BEAT

120.00 ✓

0001 SP SPRAYPAINT CHARGE

120.00 ✓

SUB-TOTAL : 240.00

TOTAL : 1,353.36

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Tanphin 97445749
up' 13/6/23 @ 10am
L/S Resurvey after repair
Tanphin @ Hyundai.com
01 day

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: