

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO SHB3645P  
 MAKE HYUNDAI  
 MODEL IONIQ

DATE: 13.06.23  
 MVA JUMANI  
 DOA: 13.06.23

**CHINA**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			<i>cut</i> \$459.40
1	REAR BUMPER CENTRE MLDG			<i>del</i> \$451.25
1	REAR BUMPER BEAM			? \$394.80
1	REAR BUMPER CLIPS			<i>del</i> \$22.00
1	REAR BUMPER TOW COVER			<i>del</i> \$98.80
1	REAR FOG LAMP			<i>cut</i> \$201.50
1	ANTENNA SMARTKEY			? \$40.60
	REAR BUMPER LOWER CENTRE MOULDING			<i>cut</i> \$155.00
	<b>SUB TOTAL</b>			<b>\$1,823.35</b>
	<b>LESS 20%</b>			\$364.67
	<b>DISCOUNTED TOTAL</b>			<b>\$1,458.68</b>
	REVERSE SENSOR			<i>del</i> \$180.00 <b>NET</b>
	REAR NUMBER PLATE			<i>cut</i> \$55.00 <b>NET</b>
	REAR BUMPER MAT			<i>del</i> \$50.00 <b>NET</b>
	<b>NET TOTAL</b>			<b>\$285.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			<i>350</i> \$400.00
	SPRAY PAINT			<i>250</i> \$300.00
	REMOVE/REFIX REVERSE SENSOR			<i>30</i> \$50.00
	<b>TOTAL LABOUR</b>			<b>\$750.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,496.68</b>

*Handwritten notes:*  
 97495744  
 13/6/23 25 pm  
 2 days  
 1/3 hour after repair  
 Handwritten signature

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Third party survey is on a "Without Prejudice" basis  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

am: ARC Repair TP(CFS0)1

**JOB CARD** Sales Order: 5900061


JC NO305557604

OMER  IS CITYCAB PTE LTD OMER NO. 7010070 IESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65551188 (O) (P)  JUNT CARD NO.	REGN NO: <b>SHB3645P</b>	MILEAGE
	MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
	MODEL <b>IONIQ(G3)</b>	DATE/TIME IN <b>13.06.2023 11:20</b>
	YR OF MANU. <b>09.10.2019</b>	TARGET DATE
	CHASSIS CODE <b>KMHC851CVLU178590</b>	COMPLETION DATE/TIME:

Accident Date: 13.06.2023  
NATURE: 3P.13.06.23

JOB DESCRIPTION

'NO                      LABOR CODE                      DESCRIPTION



RECEIVED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Work Order / Edgement Slip

Exit Pass

Vehicle No.: SHB3645P

JU CHINA

Vehicle No.:

SHB3645P

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard