

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA6998G
 Make : HYUNDAI
 Model : IONIQ(G3)

Date: 19/06/2023
 Insurance: CHINA TAIPING
 MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60
1	BOOTLID			\$2,549.70
1	BOOTLID HYUNDAI PLATE			\$24.30
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	ANTENNA SMARTKEY			\$40.50
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR BUMPER TOWING COVER			\$98.80
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
SUB TOTAL				\$4,840.65
LESS 25% DISCOUNTED TOTAL				\$3,630.49
	REAR NUMBER PLATE WITH TRIM COVER			\$50.00
	BOOTLID COMFORT TEL NO STICKER			\$40.00
	BOOTLID COMFORT LOGO STICKER			\$30.00
	BOOTLID COMFORT APP STICKER			\$30.00
	REAR BUMPER REVERSE SENSOR			\$180.00
NETT				\$330.00
	Labour Charge			
	PANEL BEATING			\$750.00
	SPRAY PAINTING CHARGE			\$600.00
	REMOVE/REFIX BOOTLID GLASS			\$120.00
	TUFF KOTE			\$60.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
TOTAL LABOUR				\$1,610.00
ESTIMATE TOTAL				\$5,570.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 297495719
 WP: 19/6/23 0430
 4/5 Resurvey after repair
 Edy

JOB CARD

Sales Order: 5900707

JC NO:305557968

Team: ARC Repair TP(CLS0)1

CUSTOMER

MS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO:

SHA6998G

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN

17.06.2023 10:45

YR OF MANU.

17.07.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164924

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 17.06.2023

Incident Nature: 3P 17.06.2023

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Confirmation Slip

Exit Pass

No.: SHA6998G

YY

Vehicle No.:

SHA6998G

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard