

(08/11/13) Web
ASS. REC. BY: mm

REF:

CS/NC 23006238/RVY3

8906

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GDF 39043

at Workshop m/s SH TRUCK AUTOMOTIVE

of 18, Brown NO

Insured: NIML

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
<u>(1)</u>	

Bal. or Market Value: 31K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 17K

Veh No: GDF 39043 Yr Regn: 2016 / SGP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NV3502.55NT c.c. 2488

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 181054 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIMC2E26Z0006645

Gen. Cond: Good / Fair / Poor / Burnt

Steering: (1) In order / Jammed / Leaked / Burnt or

Brake: (1) In order / Jammed / Leaked / Burnt or

Modi: (1) Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 7

(1) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 20/06/23

Survey held at: SH TRUCK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SG Truck Automotive Pte Ltd
18 Benoi Road
Singapore 629880
sgtruckat.com
Tel: 9021 1212

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

DATE

20/6/2022

Attention: Motor Claim Department

SHEET NO. 1 OF 1 SHEET

RE: VEHICLE NO: GBF3904S NISSAN

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	1	TAILGATE <i>bf</i>		3,550.00
2	1	REAR BUMPER <i>de</i>		1,085.00
3	1	REAR BUMPER UPPER COVER <i>X</i>		388.00
4	1	TAILGATE MOULDING <i>am</i>		487.00
5	1	TAILGATE INNER TRIM <i>X</i>		553.00
6	1	TAILGATE LOCK <i>X</i>		432.00
				\$ 6,495.00
LESS 15%				\$ 5,845.50

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
SPECIAL NET				
1	1	8 PAX <i>am</i>	\$	35.00 <i>10</i>
2	1	70KM /H <i>am</i>	\$	35.00 <i>10</i>
3	1	TAILGATE NISSAN EMBLEM <i>am</i>	\$	210.00 <i>78</i>
4	1	TAILGATE NV350 EMBLEM <i>am</i>	\$	222.00 <i>56</i>
5	1	TAILGATE URVAN EMBLEM <i>am</i>	\$	188.00 <i>55</i>
6	1	REAR NUMBER PLATE <i>X</i>	\$	35.00 <i>X</i>
7	1	REVERSE SENSOR <i>am</i>	\$	200 <i>287.00</i>

S/NO.	QTY	LABOUR & MISCELLANEOUS:	AMOUNT S\$
1	1	To remove damaged body parts with all necessary components/ attachment apply hot-works where necessary straighten front floor panel repair, reshape body dented panel in accordance to factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,200.00 <i>500</i>
2	1	To spray paint replaced/repared body parts inclusive of preparatory works and painting materials	1,000.00 <i>500</i>
3	1	To check and reconnect wiring reverse sensor	300.00 <i>50</i>
4	1	To remove and refit tailgate windscreen	150.00 <i>120</i>

Prime
Hp 90010068
4 days
4/5
20/06/23
Resy after repair

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	890E
Vehicle No.:	GBF39045
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jun 2023
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	YD25397944A
Chassis No.:	JN1MC2E26Z0006645
Maximum Power Output:	-
Open Market Value:	\$23,002.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$1,151.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	29 Sep 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$41,380.00
COE Rebate Amount:	\$13,540.00
Total Rebate Amount:	\$13,540.00

The information contained herein is correct as at 21 Jun 2023

OK



Nissan NV350 2.5M

\$33,800 Instalment \$847/mth

PREMIUM AD

Shortlist

Loan Calculator

Never too late,
never too early



Overview

Financial

Photo

Research

Depreciation

\$10,020 / year

Reg. Date

04-Nov-2016

(3yrs 4mths 13days COE left)

Lifespan

03-Nov-2036

Manufactured

2016

Mileage

-

Transmission

Manual

Engine Cap

2,488 cc

Curb Weight

1,800 kg

Fuel Type

Diesel

COE

\$17,381

OMV

\$23,002

ARF

\$1,151

Dereg Value

\$5,862 as of today

No. of Owners

4

Type of Veh

Van