

(08/11/13) wef

ASS. REC. BY: /

Tayfiker

REF:

CS/INC23006240/Try3

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Lump Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Veh No: 2NH6691H

Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E220 c.c

Colour 73852

A/C: Insured / Std / NI / NA

Sp. Reading 71144

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD2130042H052090

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/30R20

R: 275/30R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front 6

Rear 6

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 21/6/23

Survey held at Auto Bulbox

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Invs (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

☐

S + RS SI

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

# AUTO BULLOX PTE.LTD

53 Ubi Avenue 1 #01-25 Paya Ubi Industrial Park S(408934)

Business Reg No: 201919765N

Tel: 6841 5383 / Fax: 6841 6043

E-Mail: autobullox@gmail.com

To: Motor Claims Department

Date: 14/09/2022

Vehicle No: SNH6691H

Model: Mercedes Benz E220D SE Auto

## Estimated Repair Cost For SNH6691H (Mercedes Benz E220D SE Auto)

QTY	Parts	Amount
1	Front bumper	\$ 1,767.01 <i>de</i>
2	Front bumper side retainer @ SGD 68.76	\$ <i>RMx</i> 137.52 <i>Ly-de</i>
2	Front bumper mount @ SGD 145.86	\$ 291.72 <i>?</i>
1	Front bumper centre bracket	\$ 158.96 <i>ds</i>
1set	Front bumper spacer ring (set)	\$ 68.55 <i>de</i>
2 <i>A</i>	Front bumper distance sensor @ SGD 194.44	\$ 777.76 <i>nu</i>
2	Front bumper side garnish @ SGD 168.72	\$ 337.44 <i>X</i>
1	Front bumper centre air-grille	\$ 245.82 <i>?</i>
1	Front bumper centre chrome	\$ 225.74 <i>?</i>
1	Front bumper number plate garnish	\$ 78.62 <i>?</i>
1	Front bumper logo badge	\$ 78.96 <i>de</i>
1	Front bumper sponge	\$ 172.95 <i>dis</i>
1	Front bumper reinforcement	\$ 795.07 <i>?</i>
2	Front bumper tow garnish @ SGD 64.23	\$ 128.46 <i>X</i>
1set	Front bumper clips / rivets	\$ 80.00 <i>de</i>
1	Radiator grille	\$ 725.46 <i>de</i>
2	Radiator grille chrome @ SGD 145.62	\$ 291.24 <i>cut</i>
1	Radiator grille "T" bracket	\$ 29.64 <i>ds</i>
1set	Radiator grille centre ring (star)	\$ 196.84 <i>cut</i>
1set	Radiator grille clips	\$ 45.00 <i>de</i>
1set	Radiator grille centre top garnish	\$ 296.82 <i>cut</i>
1	Radiator grille centre top garnish clips	\$ 45.00 <i>de</i>
2	Headlamp assy (LED) @ SGD 4359.86	\$ 8,719.72 <i>cut</i>
2	Headlamp bracket @ SGD 181.36	\$ 362.72 <i>?</i>
2	Headlamp sealing frame @ SGD 65.46	\$ 130.92 <i>X</i>
2	Headlamp control unit @ SGD 758.88	\$ 1,517.76 <i>X</i>
2	Headlamp range adjustment @ SGD 277.18	\$ 554.36 <i>X</i>
1	Bonnet	\$ 2,649.27 <i>bt</i>
1	Bonnet logo	\$ 106.54 <i>de</i>
1	Bonnet insulator	\$ 316.25 <i>X</i>
1	Bonnet hinges @ SGD 98.76	\$ 197.52 <i>?</i>
1	Bonnet stopper @ SGD 32.01	\$ 64.02 <i>X</i>
1	Bonnet lock	\$ 197.86 <i>bt</i>
1	Bonnet bottom lock	\$ 208.65 <i>bt</i>
1set	Bonnet insulator clips	\$ 60.00 <i>X</i>
1	Front support panel	\$ 1,086.94 <i>bt</i>

1	AC condenser	\$	1,624.92	67-
1	AC condenser side air guide @ SGD 85.25	\$	170.50	?
1	AC fan motor, cowling assy	\$	1,455.26	?
1	Radiator assy	\$	1,897.54	?
1	Inter cooler assy	\$	1,347.62	?
2	Front fender @ SGD 987.86	\$ Rtx	1,975.72	X R- L4
2	Front fender inner shield @ SGD 247.54	\$	495.08	X
2set	Front fender inner shield clips	\$	120.00	X
1	Rear bumper	\$	1,602.74	de-
2	Rear bumper side bracket @ SGD 68.55	\$	137.10	de-
2	Rear bumper side mount @ SGD 145.86	\$	291.72	?
1	Rear bumper centre bracket	\$	145.62	?
1set	Rear bumper spacer ring (set)	\$	65.82	ner
2-4	Rear bumper distance sensor @ SGD 273.79	\$	1,095.16	mm-
1	Rear bumper lower	\$	795.68	all-
1	Rear bumper centre garnish	\$	228.62	X
2	Rear bumper side garnish @ SGD 148.65	\$	297.24	X
2	Rear bumper refelctor lamp @ SGD 145.76	\$	291.52	X
1	Rear bumper tow garnish	\$	45.68	de-
1	Rear bumper sponge	\$	195.60	?
1	Rear bumper reinforcement	\$	740.52	?
1set	Rear bumper clips / rivets	\$	80.00	ner
1	Bootlid panel	\$	1,935.86	Rx
1	Bootlid panel logo	\$	98.50	ner
1	Bootlid panel outer garnish	\$	296.78	X
1	Bootlid panel inner lock	\$	228.62	X
1	Bootlid weather strip	\$	225.28	?
2	Taillamp assy (LED) @ SGD 996.84	\$	1,993.68	?
1	Rear exhaust pipe	\$	2,286.73	X
1	Rear exhaust heat shield	\$	396.42	X
2	Rear exhaust pipe mounting @ SGD 118.40	\$	236.80	X
1	Rear end panel	\$	1,228.45	Ry
1	Rear end panel top garnish	\$	226.55	?
1set	Rear end panel top garnish clips (set)	\$	60.00	X
1	Spare wheel well	\$	479.61	X
Parts Sum:		\$	47,940.05	
Parts Less 10% :		\$	4,794.05	
Parts Total:		\$	43,146.00	

#### Special Nett Items

1	Rear end panel sealant	\$	80.00	X
1	Spare wheel well sealant	\$	80.00	X
1set	Rear number plate w/garnish	\$	65.00	X
1	Radiator coolant	\$	165.00	?
1set	Front number plate w/garnish	\$	65.00	4567-
Special Nett Items Total:		\$	455.00	

#### Labour & Misc Charges

Description	Amount
To Remove, Replace, Re-align & Install affected Front Damaged Areas (\$350.00 per day)	\$ 1,400.00 750
To Putty, Prep & Re-spray on affected Front Damaged Areas (\$350.00 per panel)	\$ 1,750.00 1000

To Disconnect Front Wire Harness, Electrical Components to Faciliate Repairs	\$	150.00	50
To Remove & Renew Front Distance Sensor, To Align & Calibrate Distance Programming	\$	250.00	100
To Remove, Replace, Re-align & Install affected Rear Damaged Areas (\$350.00 per day)	\$	1,750.00	750
To Putty, Prep & Re-spray on affected Rear Damaged Areas (\$350.00 per panel)	\$	1,750.00	750
To Remove & Transfer Rear Bootlid Components to Facilitate Repairs	\$	150.00	X
To Remove & Transfer Spare Tyre Components to Facilitate Repairs	\$	150.00	60
To Remove & Install Rear Exhaust to Facilitate Repairs	\$	200.00	X
To Re-programme & Re-set Star Diagnostic re-calibrate and adjust headlamp.	\$	450.00	150
To Apply Undercoating on the Affected Damaged Areas	\$	250.00	40
<b>Labour Charges Total:</b>		<b>\$</b>	<b>8,250.00</b>

**Parts Total:** \$ 43,146.00  
**Special Nett Items Total:** \$ 455.00  
**Labour Charges Total:** \$ 8,250.00  
**Total Cost Of Repair:** \$ 51,851.00  
**(Non-Inclusive of GST)**

Tauphin 97495744 / 62563561  
 'wp' 21/6/23 @ 230pm  
 c/s rising after repair  
 tauphin c/w hawtown  
 10 days

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	17/06/2023 14:30 (SGT)
Reported by	Actual Driver
Date of Accident	16/06/2023 09:00 (SGT)
Exact Location of Accident	Jurong Town Hall Rd, Singapore
Additional Location Information	JURONG TOWN HALL ROAD TOWARDS WEST COAST ROAD
	SINGAPORE
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNH6691H
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	CAR EMPIRE AUTOMOBILES PTE. LTD.
Company Reg No	201817298R
Email Address	ADMIN@CAR-EMPIRESG.COM
Mobile Phone No	(Phone) +65-69097310
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E220
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

## INSURANCE COMPANY

Name of Insurance Company	EQ Insurance Company Ltd
Policy Number / Cover Note Number	DMTTHQ23-000037

## DRIVER

Name of Driver	KHAW SOON YONG, REUBEN
NRIC No	S8944270B
Date Of Birth	05/12/1989

Occupation	Indoor
Date Of Driving Pass	08/01/2013
Driving experience	10 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88668682
Alt. Phone Number	-
Email Address	REUBEN.89@HOTMAIL.COM
Address	BLK 442A BUKIT BATOK WEST AVENUE 8 08-877 SINGAPORE 651442
Address complement	-
Postcode	651442
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	JEAN NG KAI SING
Gender	Female

#### PASSENGER 2

Name	RAELYNN KHAW KE YU
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED  
STATEMENT RECORDED BY ANNIE - PROGRESSIVE CAR CARE PTE LTD  
TEL 67415336

Are accident photos available for attachment?  
 Was there any video captured by Car Camera?

Yes  
 No

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SL60M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLV4890M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

### INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person	KHAW SOON YONG, REUBEN
Gender	Male
Phone No	(Phone) +65-88668682
Address	BLK 442A BUKIT BATOK WEST AVENUE 8 08-877 SINGAPORE 651442
Address Complement	-
Post Code	651442
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SNH6691H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

#### INJURED 2

Name of injured person	JEAN NG KAI SING
Gender	Female
Phone No	-
Address	-
Address Complement	-

Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SNH6691H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 3 :

Name of injured person	RAELYNN KHAW KE YU
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SNH6691H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 4

Name of injured person	UNKNOWN
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SL60M
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-



**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder, Date)

  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

**Sketch Plan**



The sketch plan is a grid-based diagram showing the layout of the accident scene. It includes a central vertical line with three upward-pointing arrows, and a horizontal line with three upward-pointing arrows. To the right of the grid, the following labels are handwritten:

- A: SWH669TH
- B: SL60M
- C: SLV4890M


Describe Circumstance of the Accident


REFER TO POLICE REPORT


**Declaration**

We declare the foregoing particulars are true in every respect

If you wish to claim against your own policy, please be advised that your insurer may have a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence. Kindly check with your insurer for more details.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)



**SINGAPORE  
POLICE FORCE**



T/20230616/7059

1 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20230616/7059

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 16/06/2023 19:21	Vide Report No.: D/20230616/0026	Station Diary No.:
--------------------------------------------	-------------------------------------	--------------------

**Informant's Particulars**

Name of Informant: KHAW SOON YONG, REUBEN			Address: 442A BUKIT BATOK WEST AVENUE 8 #08-877 SINGAPORE 651442		
ID Type / ID No.: NRIC NO / S8944270B			Contact No.: Home/Office: Mobile: 88668682		
Nationality: SINGAPORE CITIZEN			Email: REUBEN.89@HOTMAIL.COM		
Sex: Male	Age: 33	Date of Birth: 05/12/1989	Type of Informant: Driver		
Race: Chinese			Language: English		
Occupation: Shop sales assistant			Driving Licence Information: Class: 3,4 Date of Expiry:		

**General Information of the Accident**

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 16/06/2023 09:00	Type of Location: Main road
Location:  TOWN HALL LINK				
Weather: Clear		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: The back vehicle rear end me and I hit the vehicle in front of me				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of
SL60M	Car					0
SLV4890M	Car					0
SNH6691H	Car					0





**SINGAPORE  
POLICE FORCE**



T:20230616/7059

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T:20230616/7059

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	KHAW SOON YONG, REUBEN	ID No.	S8944270B
Related Vehicle	SNH6691H (Car)	Contact No.	88668682
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3,4 Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	Slight

Brief Details.

I was involved in a traffic accident on 16/06/2023 & time? along Jurong Town Hall Road towards west coast road, in the middle lane outside of Ivory Heights condominium before Jurong East Central. Accident happened when the car in front of me slow down and I follow suit. Suddenly, I received a huge impact from my rear and my car surge forward and hit onto the car in front of me. The impact was so big that it resulted cosmetic injury to my wife who were seated at the back of my car despite having her seat belt on. Both my wife and the driver of the last vehicle were conveyed to the hospital for treatment. She was given 7 days MC. I started to feel pains after a while and had since consulted doctor and was given 5 days of MC. Traffic police hold the footage of the front and the last car.



**SINGAPORE  
POLICE FORCE**



T:20230616/7059

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20230616/7059

**CONTINUATION OF REPORT**

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TP18 /  
PHUA TIAK YEE  
Contact No.: 65476200

Signature Of Informant:

The identity of the person making this report has  
been authenticated by Singpass. No signature is  
required.

Date/Time:  
16/06/2023 19:21

Classification Of Case:

NP168