Surveyor:	REF: CS1/LIP230	Dqy3 006258/ Rqy3	Special Instruction:
From (Person): ESTHER CHEAH Estimated Cost;	of LIBERTY Da	LS: \$ 9600 / 3 DAYS Third Parties: Claimant:	
To Inspect Vehicle No: at Workshop m/s MASTER Co of 40 TOH GUAN ROAD EA	SNB 3935G AR SPRAY SERVICE	Insured: SMW 929X	Surveyor: PRO-OPTION SERVICES Workshop: MASTER CAR SPRAY SERVICE
Policy No: Sum Insured: Make of Veh: (Client's Record)		Claim No: AVS22/3568 Excess: 17/12/2022	
Date/Time: Person Contacted: Vehicle IN / OUT Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 7 days) Date/Time: 07/07/23 Submit Final Fig \$2685 , 3 days (Red \$ 6915 / 72 %; Original 3 days)			
Para(1): Parts found not replaced (To highlight R or UB, LR, Etc) Para(2): Comments on consistency of damages (Parts Not Consistent: NC)			
Para(3): Nett Value			
Market Value Salvage Value Nett Value	:_103,103.00	Inspected/ Evaluated by: 2) Date/Time	Fee Charged: Date: Basic & Add Transport Photos Others Total
3) Date/TimeFi	le Pass to	4) Date/Time	File Return to