



Your Ref: AVS22/3568

Date: 13th July 2023

Our Ref: CS1/LIP23006258/Dqy3e2

M/s Liberty Insurance Pte Ltd

51 Club Street, #03-00

Liberty House

Singapore 069428

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SNB 3935G

INSURED VEHICLE: SMW 929X

ACCIDENT DATE: 17/12/2022

We thank you for your instruction on 20/06/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SNB 3935G from M/s Pro-Option Services.
- b) Final Repair Bill of SNB 3935G from M/s Master Car Spray Service.
- c) Singapore Accident Statement of Vehicles SNB 3935G and SMW 929X.
- d) Colour damaged vehicle photographs of SNB 3935G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SNB 3935G
Make & Model	: B.M.W. 640I Gran Coupe M Sport Led SR NAV HUD
Chassis Number	: WBA6A02080DZ10439
Registration Date	: 21 Aug 2012
Engine Capacity	: 2979 cc

- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.