


A.S. REC. BY: Taujkh

REF: 03/11121009250/TITFS

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: FBL6114D Yr Regn: 2017 / jan  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Yamaha MT-03 c.c. 321  
Colour: Black A/C: Insured / Std / NI / NA  
Sp. Reading: - T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: MH 3RHO 7K000004586  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modl: Nib / S/Rim / STD A/Rim or  
Tyre Size: F: 110/60R17  
R: 150/60R17  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front 5 mm Rear 5 mm  
R/Bal. 5 mm R/Bal. 5 mm  
L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
D.O.A. \_\_\_\_\_ D.O.I. 12/3/21  
Survey held at Cadre Auto.  
Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS WP PRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>No GIA.</u>
	<b>CHECK WITH INSURANCE TP DID NOT MAKE REPORT. NO GIA REPORT</b>
	<b>SUBMIT PRS REPORT</b>

Date/Time, File Pass to?  : Preli. Report  
1)  : Final Report  
Date/Time, File Return to?  
2) \_\_\_\_\_  
Report Format : PRS  
Lump Sum / I.B.F. (%) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_  
Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
_____ \$ + RS. _____ \$	
Photos	
Others	
TOTAL	