

(08/11/13)

Wof

ASS. REC. BY: James

REF:

CCP/LPC 23006294/Rya3

2780

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 75444at Workshop m/s R&Sof Plonker Seave

Insured:

LPC

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

67K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Repair LM K- 38K

Veh No:

SLQ 75444

Yr Regn:

2017 / JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru XV1.6i-sc.c 1600

Colour

BLACKA/C: Insured / Std / NI / NA

Sp. Reading

110980T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

7F14P3KC5H205362Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/06/23

D.O.I.

22/06/23

Survey held at

R&S

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS SI☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	274D
Vehicle No.:	SLQ7544U
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jun 2023
Vehicle Make:	SUBARU
Vehicle Model:	SUBARU XV 1.6I-S AWD CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	FB16Y596994
Chassis No.:	JF1GP3KC5HG205362
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$15,387.00
Original Registration Date:	21 Jul 2017
First Registration Date:	21 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$15,387.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2027
PARF Rebate Amount:	\$10,770.00
COE Expiry Date:	20 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$17,421.00
Total Rebate Amount:	\$28,191.00

The information contained herein is correct as at 24 Jun 2023

OK

\$65,800 Instalment \$1,094/mth

PREMIUM AD

 Shortlist Get Warranty Loan Calculator**mycarforum****TRENDING DISCUSSIONS****Diesel Particulate Filter
(DPF) cleaning the house**

READ MORE >

Overview Financial Photo Research

Depreciation	 \$14,760 / year
Reg. Date	31-May-2017 (3yrs 11mths 6days COE left)
Manufactured	 2016
Mileage	85,352 km (14.1k / year)
Transmission	Auto
Engine Cap	1,600 cc
Road Tax	 \$744 / year
Power	84.0 kW (112 bhp)
Curb Weight	 1,480 kg
COE	 \$46,489
OMV	 \$15,421
ARF	 \$15,421
Dereg Value	 \$28,314 as of today
No. of Owners	 2