

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23006318/Tqp3m4		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	07-07-2023 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLE 7381K	Veh. Ir	nspected	SHA 3755K	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1228378-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	21/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	JTDKB3FU703563561	Colou	r	BLUE	
	Odometer	687974	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65R15	WEST	LAKE	6 mm	
	L/H Front Tyre	195/65R15	WEST	_AKE	6 mm	
	R/H Rear Tyre	195/65R15	WEST	_AKE	6 mm	
	L/H Rear Tyre	195/65R15	WEST	LAKE	6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	20/06/2023	Inspec	tion Date	21/06/2023	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.		Remarks				
	A)THE INSPECTION B)IN ACCORDANCE	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					