

ASS. REC. BY:

REF:

HLA/23006328/Kgy3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$167k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

LB1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMS 88662

Yr Regn:

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Lexus ES300

c.c

2487

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

65112

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTHB21B130 2048030

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/45R18

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

11/6/23

D.O.I.

28/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/7 11:00 AM @ 53001 Color (red 84985, 48%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trlp:

1

Survey Fee:

Transportation

S + RS. SI

Fuel

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

MER-TP

Lump Sum / I.B.d. (\$

5300

Date: 22/06/2023

Vehicle No: SMS8866L

Model: LEXUS ES300H 4DR SEDAN

Chassis: JTHB21B1302048030

Reg.Year: 2019

Not Notified
Running After Repair
2 days
L1Pmp 85300ch

Third Party Insurer: HL ASSURANCE

Third Party Veh No: SKR6860U

Date of Accident: 11/06/2023

Estimator: VICTOR

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT GRILLE ASSY WITH CHROME	1		<i>CM</i> \$1,660.00
2	FRONT GRILLE LOGO <i>1180</i>	1		<i>CM</i> \$1,370.00
3	FRONT RADAR SENSOR <i>2025</i>	1		<i>Short</i> \$2,125.00
4	FRONT BUMPER	1		<i>CM</i> \$1,295.00
5	FRONT REINFORCEMENT	1		<i>n</i> \$720.00
6	FRONT SPONGE	1		<i>CM</i> \$240.00
7	FRONT SENSORS	2	\$320.00	<i>CM</i> \$640.00
SUB TOTAL				\$8,050.00
LESS 10%				-\$805.00
PARTS TOTAL				\$7,245.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT GRILLE CLIPS	1		<i>n</i> \$100.00
2	FRONT BUMPER CLIPS	1		<i>new</i> \$120.00
3	FRONT LICENSE PLATE WITH HOLDER	1		<i>new</i> \$80.00
S/N TOTAL				\$300.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRT ACCIDENT AREA.

200
\$700.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.

\$500.00 *250*

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSORS.

\$120.00 *60*

TO PROGRAMME FRONT RADAR SENSOR.

\$1,200.00 *350*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

new \$100.00 *X*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 *20*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$2,740.00

TOTAL \$10,285.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

11 Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	751F
Vehicle Details	
Vehicle No.:	SMS8866L
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES300H 4DR SEDAN (AUTO) EXECUTIVE
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	A25AN058426
Chassis No.:	JTHB21B1302048030
Maximum Power Output:	160.0 kW (214 bhp)
Open Market Value:	\$45,594.00
Original Registration Date:	14 Aug 2019
First Registration Date:	14 Aug 2019
Transfer Count:	1
Actual ARF Paid:	\$55,832.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Aug 2029
PARF Rebate Amount:	\$41,874.00
Intended COE Rebate Details	
COE Expiry Date:	13 Aug 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,001.00
COE Rebate Amount:	\$24,570.00
Total Rebate Amount:	\$66,444.00

The information contained herein is correct as at 21 Jun 2023

OK