

ASS. REC. BY: Tauph REF: CS / SMR 23 0063 76 / 7ny3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 467K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seer: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S

Veh No: YPS952P Yr Regn: 20.7.1 April.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mitsubishi FEB21 c.c. 2998
 Colour: White A/G: Insured / Std / NI / NA
 Sp. Reading: 340655 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: FEB 21 E A 21264
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: NI / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/85R15
 R: 2 - (D)
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front		Rear
R/Bal. <u>8</u> mm		R/Bal. <u>8/8</u> mm
L/Bal. <u>8</u> mm		L/Bal. <u>8/8</u> mm
D.O.A. _____		D.O.I. <u>25/6/27</u>

 Survey held at Acc N-51
 Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or
Frt O/S
 The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Rep. Format: _____
 Lump Sum / L.B.A. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee:	
Transportation:	
S + RS	
Photos	
Others	
TOTAL	

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SHIN KHAI CONSTRUCTION PTE LTD

27 KAKI BUKIT CRESCENT

SINGAPORE 416258

Contact : 87543132, 86161386

TAX INVOICE

Repair Code : CLM15950

Date in : 22/06/2023

Vehicle Num. : YP5952P

Model : MITSUBISHI CANTER FEB21ER3SDEB (CBU)

Chassis/Eng# : FEB21EA21264/4P10C43786

Parts and Labour Assesment

Description of part	Qty	Unit Price		Amount
FRONT BUMPER	1	1010.30	?	1,010.30
FRONT BUMPER RH BRACKET	1	183.10	?	183.10
FRONT BUMPER RH SIDE	1	253.70	de	253.70
FRONT CORNER PANEL GARNISH END COVER RH	1	41.95	cut	41.95
FRONT CORNER PANEL GARNISH RH	1	524.55	dis	524.55
FRONT GRILLE	1	1053.14	X	1,053.14
FRONT GRILLE 'CANTER' EMBLEM	1	81.70	X	81.70
FRONT GRILLE 'LOGO' EMBLEM	1	85.05	^	85.05
FRONT PANEL	1	1122.45	X	1,122.45
FRONT PANEL 'FUSO' EMBLEM	1	154.96	X	154.96
FRONT RH DOOR	1	2071.55	bb	2,071.55
FRONT RH DOOR ARCH GARNISH	1	75.10	cut	75.10
FRONT RH DOOR ARCH RUBBER SEAL	1	121.35	X	121.35
FRONT RH DOOR HINGE (LOWER)	1	125.00	?	125.00
FRONT RH DOOR HINGE (TOP)	1	125.00	?	125.00
FRONT RH DOOR INNER TRIM BOARD	1	638.89	?	638.89
FRONT RH DOOR MECHANISM LOCK	1	402.84	X	402.84
FRONT RH DOOR PILLAR (OUTER)	1	796.00	Ry	796.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

SHIN KHAI CONSTRUCTION PTE LTD
 27 KAKI BUKIT CRESCENT
 SINGAPORE 416258

Contact : 87543132, 86161386

TAX INVOICE

Repair Code : CLM15950
 Date in : 22/06/2023
 Vehicle Num. : YP5952P
 Model : MITSUBISHI CANTER FEB21ER3SDEB (CBU)
 Chassis/Eng# : FEB21EA21264/4P10C43786

FRONT RH DOOR WEATHER STRIP SEAL	1	224.99	?	224.99
FRONT RH HEADLAMP	1	501.40	Cur ✓	501.40
FRONT RH SIDE MIRROR	1	130.00	un ✓	130.00
FRONT RH SIDE MIRROR ROUND COVER	1	15.00	mi ✓	15.00
FRONT RH STEP GARNISH	1	358.00	wt ✓	358.00
FRONT RH STEP PANEL	1	459.00	Ry ✓	459.00
FRONT SIDE LAMP RH	1	222.53	mi ✓	222.53
FRONT SIGNAL LAMP RH	1	266.35	mi ✓	266.35
Subtotal before discount				11,043.90
Percentage discount 25%				2,760.98
Sub-total 1				8,282.93
FRONT CORNER PANEL GARNISH RH CLIPS - SET	1	30.00	2one ✓	30.00
FRONT GRILLE EMBLEM CLIPS - SET	1	50.00	?	50.00
FRONT RH DOOR ARCH GARNISH CLIPS - SET	1	20.00	un ✓	20.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	3one ✓	50.00
FRONT RH DOOR OUTRT SEAL	1	120.00	6 q wt ✓	120.00
FRONT RH DOOR STICKER	1	400.00	250.	400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

SHIN KHAI CONSTRUCTION PTE LTD
 27 KAKI BUKIT CRESCENT
 SINGAPORE 416258

Contact : 87543132, 86161386

TAX INVOICE

Repair Code : CLM15950
 Date in : 22/06/2023
 Vehicle Num. : YP5952P
 Model : MITSUBISHI CANTER FEB21ER3SDEB (CBU)
 Chassis/Eng# : FEB21EA21264/4P10C43786

Subtotal before discount	670.00
Percentage discount 0%	0.00
Sub-total 2	670.00
Parts-total	8,952.93

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	40	80.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	60	80.00
To remove, reinstall dashboard fascia, meter reading and etc. (to FR)	pluto 200 ?	300.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800	1,400.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	700	1,400.00
To apply anti-rust chemical on repaired and replaced panel.	40	120.00
Labour Total		3,380.00
Parts & Labour Total		12,332.93

*** This is a computer-generated document which requires no signature.***

page 3

Tanphiba 97495779
 WP' 22/6/23 @ 5pm
 L/S Resurvey after repair
 Tanphiba @ lkk auto.com
 o'clock

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

VEHICLE NO: YP 5952 P	MAKE & MODEL: Mitsubishi Fuso	AUTO / MANUAL
DATE OF ACCIDENT:	22 / 06 / 2023	CC: 3.0
TIME OF ACCIDENT:	0750 HRS	
LOCATION OF ACCIDENT:	Bukit Batok St 11 towards Bukit Batok West Ave 6 before Bukit Batok West Me 6	
EXACT PURPOSE USE DURING ACCIDENT:	EMPLOYMENT / PRIVATE USE / PRIVATE HIRE	
NAME OF OWNER:	Shm Khai Construction Pte Ltd	
TEL NO:	H/P: 8754 3132	OFFICE: HOME:
NRIC:	200722471K	
ADDRESS:	27 Kaki Bukit Crescent Kaki Bukit Techpark 1 S 416258	
EMAIL:	PAT@SHINKHAI.COM	
CLAIM TYPE:	OD / THIRD PARTY / REPORTING ONLY	
FLEET POLICY:	YES / NO	
INSURANCE COMPANY:	Great American	
TYPE OF COVERAGE:	Comprehensive / Third Party / Third Party Fire & Theft	
POLICY NO:	MOMVC 00000 8934-02-000	
NAME OF DRIVER:	AS ABOVE / IF NO: Mamun Md Al	
NRIC:	G 81975 84T	ANY PASSENGER: (6C 16M)
DATE OF BIRTH:	10 / 11 / 1984	LICENCE PASSED DATE: 21 / 03 / 2019
OCCUPATION:	OUTDOOR / INDOOR	
GENDER:	MALE / FEMALE	
CONTACT NO:	H/P: 8616 1386	OFFICE: HOME:
ADDRESS:	As above	
EMAIL:		
DOES DRIVER OWNED ANY VEHICLE:	NO / IF YES, REG NO:	INSURER:
RELATIONSHIP:	Employee	
WEATHER CONDITION:	CLEAR / RAINING / OTHERS:	
ROAD SURFACE:	DRY / WET / OTHER:	
ANY INJURIES:	NO / IF YES, WHO?	
NAME & CONTACT:		
NAME & CONTACT:		
POLICE REPORT:	NO / IF YES, WHERE?	
NOTICE OF INTENDED PROSECUTION GIVEN?	NO / IF YES, WHO?	
VEHICLE B REG NO:	SG 5960 J	ANY PASSENGERS: unknown
NAME OF DRIVER:	Thiagarajah A/L Krishnan	CONTACT NO: 8010 6037
VEHICLE C REG NO:		ANY PASSENGERS:
VEHICLE D REG NO:		ANY PASSENGERS:
VEHICLE E REG NO:		ANY PASSENGERS:
VEHICLE F REG NO:		ANY PASSENGERS:
VEHICLE G REG NO:		ANY PASSENGERS:
ANY WITNESS? IF YES, NAME:		WITNESS CONTACT:
WAS THERE ANY VIDEO CAPTURE?	YES / NO	
WAS THERE ANY AUDIO RECORDED?	YES / NO	
ACCIDENT SCENE PHOTOS TAKEN?	YES / NO	
ACCIDENT PORTION:	... : Front Right portion	
Have you been approach by unknown person soliciting (s) /-offering accident claims assistance?	YES / NO	
WORKSHOP PARTICULAR:	Twincar Automotive Pte Ltd	
CONTACT NO:	68420051 / 67440510	
CONTACT PERSON:	Steve 8821 5151	
FAX NO:	67410510	
WORKSHOP EMAIL:	sales@n51.com.sg	

Describe Circumstance of the Accident

As of above date and time, I was driving my vehicle
(YP 5952 P) along Bukit Batok St 11 towards Bukit Batok
West Ave 6. Right before Bukit Batok West Ave 6, I slowed
down and stopped my vehicle due to traffic. My vehicle
was stationary. Vehicle B (SG 5960J) turned into from Bukit
Batok West Ave 6 from the opposite side of the road.
While doing so, vehicle B whole right portion grazed along
my vehicle Front Right Portion

Video footage Attached.

Declaration

I/We declare the foregoing particulars are true in every respect.



[Signature]

Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



marun

marun

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

