

Ass. No. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insured Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claim No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC6364D Yr Regn: 2021, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mini One c.c. 1499

Colour: Beige A/C: Insured / Std / NI / NA

Sp. Reading: 21661 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMW22DK0102R46195

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R16

R: 195/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 26/06/23

Survey held at Bifrost

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

TP Check

COE Expiry: _____

Estimate given during: Yes ()
1st Survey: No ()

MV: _____

PV: _____

Nett: _____

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

Formal:

un / LRP / G