

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





| AUTOMOBILE INSPECTION REPORT                        |  |  |         |                       |            |  |
|---|--|--|---------|-----------------------|------------|--|
| INCOME INSURANCE LTD                                |  |  | Ref:    | NS/INC23006389/Tnp3e2 |            |  |
| 75 BRAS BASAH ROAD<br>INCOME CENTRESINGAPORE 189557 |  |  | Date:   | 04-07-2023<br>INC4    |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM          |  |  |         |                       |            |  |
|   | Insured Veh.                                       | FBF 7197P  | Veh. Ir | nspected              | SHC 7662H  |  |
|   | Policy No.   |  | Cover   | age (\$)              | 0.00       |  |
|   | Claim No.  | MT/1228837-002   | Exces   | s (\$)                | 0.00       |  |
|   | Assign From  |  | Assign  | n Date                | 23/06/2023 |  |
| 2. Vehicle Particulars & Condition                  |  |  |         |                       |            |  |
|   | Make & Model                                       | BYD E6 (ME-2)  | c.c     |                       | 0          |  |
|   | Engine No.   | HIDDEN   | Year o  | f Reg.                | 2022       |  |
|   | Chassis No.  | LC0CE4DC7N0037358  | Colou   | r                     | YELLOW     |  |
|   | Odometer   | 61390  | Steerii | ng                    | IN ORDER   |  |
|   | Brakes   | IN ORDER   | Modifi  | cation                | SPORTS RIM |  |
|   | General  | GOOD   |         |                       |            |  |
| 3. Conditions of Tyres                              |  |  |         |                       |            |  |
|   |  | Size   | Make    |                       | Balance    |  |
|   | R/H Front Tyre                                     | 215/55 R17   | DURAT   | URN                   | 6 mm       |  |
|   | L/H Front Tyre                                     | 215/55 R17   | DURAT   | URN                   | 6 mm       |  |
|   | R/H Rear Tyre                                      | 215/55 R17   | DURAT   | URN                   | 6 mm       |  |
|   | L/H Rear Tyre                                      | 215/55 R17   | DURAT   | URN                   | 6 mm       |  |
| 4.  | I. Description of Damages                          |  |         |                       |            |  |
|   | THE VEHICLE SU                                     | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.   |         |                       |            |  |
|   | DAMAGES SEE DETAILS.                               |  |         |                       |            |  |
| 5.  | General Information                                |  |         |                       |            |  |
|   | Accident Date                                      | 22/06/2023   | Inspec  | tion Date             | 23/06/2023 |  |
|   | Survey held at                                     | COMFORTDELGRO ENGINEERING PTE LTD  |         |                       |            |  |
|   |  | 59 LOYANG DRIVE<br>SINGAPORE 508969  |         |                       |            |  |
| 5a.   |  | Remarks  |         |                       |            |  |
|   | A)THE INSPECTION B)IN ACCORDANCE                   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |         |                       |            |  |
| 5b.   |  | Estimate Days of Repair  |         |                       |            |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days |  |         |                       |            |  |