COMFORTDELGRO

ENGINEERING	ENG	INE	ESI	NG'
-------------	-----	-----	-----	-----

Ou Da	Job Ref No : 305558569 ENGINEERING ComfortDelGro Engineering Pte Ltd				
FIN	59 Loyang Drive Singapore 508969 ALIZATION FORM Fax: 6546 8156				
То	LKK Fax:				
Attr	TAUFIKH				
Veh	cle Reg No. : SHA7062A Date of Accident : 22.06.2023				
The	survey and estimates of the repairs of the above-mentioned vehicle are as follows:-				
1.	The repair job shall bill to: INCOME GBJ2249K				
2.	The finalized amount shall be:				
	(a) Spare Parts after List discount				
	(b) Labour Charges (include advertisement stickers etc,if any)				
	Total for Part-By-Part Repair Cost				
	(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost \$5,500.00 \$5,500.00				
3.	Estimated normal period for repairs: 3 working days.				
4. We shall treat the above amount as Correct and Confirmed if there is no reply from y within 7 working days					
5.	Thank you for your assistance. We confirm the estimates and finalized amount				
	Signature: Signature: Csee fo (dev)				
	Name : LIM T S Name : TAUFIKH				
	Tel : 62148398 Date :				
	Fax : 65468156				
For	official Use Only				

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees		2000		
4. LTA Search Fee / GEARS	\$26.75 / \$2.00	Y		
5. Medical Fees (on behalf of				
driver, if applicable)				
6 Overrun				

Remarks	:1				
				_	