



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC23006393/Tnp3m4

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 04-07-2023

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 4616H	Veh. Inspected	SH 8873C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1228685-002	Excess (\$)	0.00
Assign From		Assign Date	22/06/2023

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHC851CVJU103501	Colour	BLUE
Odometer	590968	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	6 mm
L/H Front Tyre	195/65R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65R15	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/06/2023	Inspection Date	22/06/2023
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------