



Your Ref: TWK/SW/1129.20

Date: 11th July 2023

Our Ref: CS1/LAW23006406/Uvy3m4

M/s Income Insurance Ltd

C/o Securus Legal LLC

101 Cecil Street

#14-08 Tong Eng Building

Singapore 069533

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FN 9068B

INSURED VEHICLE: SLR 2377M

ACCIDENT DATE: 12/10/2018

We thank you for your instruction on 26/06/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FN 9068B from M/s Constant Appraiser Services.
- b) Survey report by Ajax Inspection Services Pte Ltd with colour photographs.
- c) Singapore Accident Statement of Vehicles FN 9068B and SLR 2377M.
- d) Police Report of Vehicles FN 9068B and SLR 2377M.
- e) Final Repair Bill of FN 9068B from M/s Moto 51 Pte Ltd.
- f) Colour damaged vehicle photographs of FN 9068B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FN 9068B
Make & Model	: Honda CB400F2T
Chassis Number	: NC311401303
Year of Registration	: 1996
Engine Capacity	: 399 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.