

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD CS3/HSB23006419/Kvp3m4 Ref: 10 MARINA BOULEVARD #48-01 MARINA BAY Date: 06/07/2023 FINANCIAL CENTRE TOWER 2SINGAPORE Code: HSB ATTN: KHOR SAW THENG Policy Particulars :- (THIRD PARTY CLAIM) 1. **SHC 1058S SDP 250M** Insured Veh. Veh. Inspected 0.00 Policy No. Coverage (\$) S3M04NN0 0.00 Claim No. Excess (\$) KHOR SAW THENG 26/06/2023 **Assign Date** Assign From 2. **Vehicle Particulars & Condition** HYUNDAI AVANTE (A) 1591 Make & Model C.C **HIDDEN** Engine No. Year of Reg. 2009 KMHDU41BR9U757000 METALLIC SILVER Chassis No. Colour Odometer 189683 KM **IN ORDER** Steering **IN ORDER** STANDARD ALLOY RIM Modification **Brakes** GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 185/65R15 YOKOHAMA 8 mm L/H Front Tyre 185/65R15 YOKOHAMA 8 mm 7 mm YOKOHAMA R/H Rear Tyre 185/65R15 L/H Rear Tyre 185/65R15 YOKOHAMA 7 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 23/06/2023 **Inspect Date / Time** 03/07/2023 (10:40 AM) **Accident Date** KING'S AUTO REPAIR & SERVICE PTE LTD Survey held at 176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/HSB23006419/Kvp3m4

Estimate Days of Repair

Inspected By

5b.

KONG SENG CHEONG

Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

NEOD Anto Ornanticut OAE Lineard American

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser