



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HL ASSURANCE PTE LTD
11 KEPPEL ROAD
#11-01 ABI PLAZASINGAPORE 089057

Ref: CS3/HLA22002837/Dny3e2-1

Date: 03/07/2023

Code: HLA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMP 3046K	Veh. Inspected	SLR 2303B
Policy No.	MP319845	Coverage (\$)	0.00
Claim No.	MPC03267/GN	Excess (\$)	0.00
Assign From	LYNN ROMEO	Assign Date	26/06/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS GS250	c.c	3456
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JTHBS1BL505002599	Colour	BLACK
Odometer	174135 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 R18	YOKOHAMA	6 mm
L/H Front Tyre	235/45 R18	YOKOHAMA	6 mm
R/H Rear Tyre	235/45 R18	YOKOHAMA	6 mm
L/H Rear Tyre	235/45 R18	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/03/2022	Inspection Date	28/03/2022
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
--	-----------------------