

(08/11/13) wof

ASS. REC. BY: TomREF: CS3/A1823006435/Rap3

9860

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKU 4737Kat Workshop m/s Carportof Pioneer Rd North #01-24

Insured:

MS

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

39K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKU 4737K

Yr Regn:

2015 / SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA AXIO 1.5X A

c.c

1496

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

138936

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NRE 610003995

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/06/23

D.O.I.

26/06/23

Survey held at

Carport

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 2KESTIMATE RANGE OF REPAIR / NO. OF DAYS - (3K-4K) / 6 days

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	986B
Vehicle No.:	SKV4737K
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	AXIO 1.5X A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	2NR8476321
Chassis No.:	NRE1610003995
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,529.00
Original Registration Date:	19 Sep 2015
First Registration Date:	19 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$8,529.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Sep 2025
PARF Rebate Amount:	\$5,117.00
COE Expiry Date:	18 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,089.00
COE Rebate Amount:	\$12,685.00
Total Rebate Amount:	\$17,802.00

The information contained herein is correct as at 29 Jun 2023

OK

Toyota Corolla Axio 1.5A X

\$35,800 Instalment \$1,152/mth

Shortlist

Get Warranty

Loan Calculator



Overview Financial Photo Research

Depreciation	<i>i</i> \$16,720 / year
Reg. Date	26-Jun-2015 (1yr 11mths 27days COE left)
Manufactured	<i>i</i> 2013
Mileage	73,000 km (9.1k / year)
Transmission	Auto
Engine Cap	1,496 cc
Road Tax	<i>i</i> \$682 / year
Power	80.0 kW (107 bhp)
Curb Weight	<i>i</i> 1,090 kg
COE	<i>i</i> \$61,000
OMV	<i>i</i> \$14,586
ARF	<i>i</i> \$5,000
Dereg Value	<i>i</i> \$14,900 as of today
No. of Owners	<i>i</i> 2

Type of Veh **Mid-Sized Sedan**