

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/06/2023

User ID : GohKK2

Section A - Accident Details	
Registration Number	SG5529Y
Case Reference Number	BUS/05/23/7030
Registration Date	6/11/2017
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	VOLVO
Name of Driver	Murugan A/L Pariasamy
Type of Accident	Head to Rear
Accident Date and Time	15/5/2023 9:43 AM
Accident Reported Date and Time	8/6/2023 12:21 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SG5529Y - REAR PORTION PC3042D (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	24/6/2023 10:05 AM
Chassis Number	YV3S4P922HA183452
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,240.00	\$0.00
Total Spray Cost	\$772.00	\$0.00
Total Spare Part Cost	\$99,567.82	\$0.00
Total Other Cost	\$2,000.00	\$0.00
TOTAL COST	\$106,579.82	\$0.00
Lump Sum Total	\$106,600.00	\$0.00
Number of Repair Days	18.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	24/06/2023 10:39 AM	
Signature	<div>×</div>	<div>×</div>
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/06/2023

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$4,240.00						
Total Labour			\$4,240.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$772.00						
Total Spray Painting & Panel Beating			\$772.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TOWING CHARGE			\$500.00						
TO ALIGN CHASSIS			\$1,000.00						
TO APPLY RUST-PROOFING ON AFFECTED AREA			\$500.00						
Total Other Costs			\$2,000.00						
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
	Body	A11-00691	REAR END AIRCON DOOR	1.00	\$6,051.05	10.00	\$5,445.95	Replace	
			ENGINE COMPLETE	1.00	\$90,000.00	10.00	\$81,000.00	Replace	
		DEL-00625	BOLT.6" PLATED SPRING LOADED.DOOR (FOR A11-00865)	2.00	\$40.65	10.00	\$73.17	Replace	
	VM	RSM-00111	RUBBER BUFFER	2.00	\$92.98	10.00	\$167.36	Replace	
	Body	B11-00081	REAR BUMPER PANEL	1.00	\$305.63	10.00	\$275.07	Replace	
	Body	B11-00082	REAR BUMPER PANEL	1.00	\$305.63	10.00	\$275.07	Replace	
	VE	ELU-00486	NUMBER PLATE LIGHT	1.00	\$145.40	10.00	\$130.86	Replace	
	Body	PLA-00798	NO PLATE RECESS PAN	1.00	\$321.15	10.00	\$289.03	Replace	
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	
		A11-00865	DOOR.LOWER BOOT	1.00	\$3,301.67	10.00	\$2,971.50	Replace	
		ELU-00486	NUMBER PLATE LIGHT	2.00	\$216.48	10.00	\$389.66	Replace	
		DES-00227	GAS JACK STAY;530N;RR ENG DOOR (FOR A11-00880)	2.00	\$1,086.00	10.00	\$1,954.80	Replace	
		A11-00710	TOP REAR SERVICE DOOR	1.00	\$3,095.05	10.00	\$2,785.55	Replace	
		A11-00880	BOOT DOOR ASSEMBLY.RR ENG SER Dr 3 HINGE	1.00	\$4,149.78	10.00	\$3,734.80	Replace	
Total					\$109,186.47		\$99,567.82		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									