

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC2314X

Make : HYUNDAI

Model : IONIQ(G2)

Date: 24/06/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 481.10
10	FRT BUMPER CLIPS			\$ 22.00
1	FRT BUMPER SIDE BRACKER LH			\$ 28.00
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50
1	HEADLAMP LH			\$ 2,110.30
1	FRT BUMPER SIDE MOULDING LH			\$ 93.60
1	DAY LIGHT LH			\$ 642.50
1	FRT FENDER BLUE-DRIVE EMBLEM LH			\$ 26.60
1	FRT WHEEL COVER LH			\$ 217.20
1	FRT FENDER SHIELD LH			\$ 164.70
	SUB TOTAL			\$ 4,154.50
	LESS 20%			\$ 830.90
	DISCOUNTED TOTAL			\$ 3,323.60
				\$ -
	Labour Charge			
	PANEL BEATING			\$ 750.00
	SPRAY PAINTING CHARGE			\$ 600.00
	CHECK ALL LIGHTING			\$ 60.00
	TOTAL LABOUR			\$ 1,410.00
	ESTIMATE TOTAL			\$ 4,733.60

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphui 97495749
 'wp' 26/6/23 1140
 2 days
 L/S Resurvey after repair
 Tanphui C/Chanbun

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Workshops205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

Date/Time: 24.06.2023 10:08

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5901537

JC NO305558664

CUSTOMER

CUSTOMER NAME: COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO: 7010045

ADDRESS: 383 SIN MING DRIVE
Singapore SINGAPORE 575717

TEL (R) 65508755

(O)

(P)

SCOUNT CARD NO.

REGN NO.:

SHC2314X

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN
24.06.2023 08:30

YR OF MANU.

13.02.2020

TARGET DATE

CHASSIS CODE

KMHC851CVLU189208

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 23.06.2023

NATURE: 3P 23.06.2023

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.:

SHC2314X

YY

Vehicle No.:

SHC2314X

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard