		-
		manage way of suffer and
		Tauph
700	BEC BY	The state of the s
247.50	11CC. 01.	I Table

REF:

NS/ (N C 23006479/Tvp3

· ·	21 CHAINTEIA I.
From: Date:	Veh No: 9414772P-Yr Regn: 2022 Jul
Estimated Cost:	Type: M. Gar/ M. Gyalo / Pyra
OD / WS / TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / - Truck / Trailer or
To Inspect Vehicle No:	Distriction in the second
at Workshop m/s	c.c / +/V
of	9 C 9 GILL
Insured: SNE 6211B	Sp.Reading 75799 T/Radio: Insured / Std / NI / NA Eng/No:
Policy No.	
Claims No. MT/1229007-002	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Cilient's Record)	Brake: Inorder/Jammed/Leaked/Burnt or
Make of Veh;	Modi: NILLS/Rim / STD A/Rim or
	Tyre Size: F: /95
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
Ball or Market Value:	Front Des Marke
IDAC Accident Rport Consistent? ; Yes or No	P/Rel
GIA / PR Seen: Consistent?: Yes or No	Milm R/Ball, mm
Est Repairs: days Res.: Yes or No	D.O.A. 24/6/2023 . D.O.L. 0
Lum Sum: % 3 Val.: Yes or No	Survey held at 0.0.1. 2.6 6 23
CA / REV / REP. / 24 HRS	1600000
Date: N / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop- or
	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	E SOU GO A COMPON.
1/7/23 Final fig \$3623.45 confirmed by e	mail (Red 2705.31, 42%)
Date/Time, Fie Pass to?	
. Fren. Report	ays Of Repair: 2
Date/Time, File Return to?	esurvey No. of Trip: Survey Fee:
2/7/22 to maint	Transportation:
a) 3/1/23-typist Add Fee:	:Site Insp (\$)s+Rssi
Reperformer: TP	: Interview (\$) Photos
Lump Sum / L.B. J. CF \$3623.45	:Tech, Invs (\$) Others
)	:Weellend (\$
	TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA7770P

Make

: Toyota

Model : Prius Date: 26/06/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price		Amount	
	FRONT FENDER SUB ASSY RH			\$	1,111.93	H-
	FRONT FENDER HYBRID EMBLEM RH			\$	86.50	
1	FRONT FENDER SHIELD RH			\$	198.50	1
1	FRONT BUMPER COVER			\$	586.18	
-	FRONT BUMPER SIDE BRACKET RH			\$		defo
10	FRONT BUMPER CLIPS			\$		ne
1	HEADLAMP RH			\$	2,735.28	
1	FRT BUMPER SIDE GRILLE RH			\$	85.10	
1	WHEEL RIM FRT RH			\$	1,570.55	nn
					1,010.00	Ke /
	SUB TOTAL			\$	6,478.34	
	LESS 25%			\$	1,619.59	
	DISCOUNTED TOTAL			\$	4,858.76	
				\$		
	Labour Charge					200
	PANEL BEATING			\$	750.00	550
	SPRAY PAINTING CHARGE			\$	600.00	500
	CHECK LIGHTING			\$	60.00	X
	TUFF KOTE			\$	60.00	30
	TOTAL LABOUR			\$	1,470.00	
	ESTIMATE TOTAL			\$	6,328.76	
	TOTAL	1		Ψ	0,320.76	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taughm 9749 979

White the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" bas

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Compa

- Third party survey is on a "Without Prejudice" basis
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Cain:



ComfortDelGro Engineering Pte Ltd.

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

Date/Time: 452 and Singapers 609286 : 02

REGN NO.: SHA7770P

TOYOTA

Page: 1

Team: JSTOMER ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5901626

JC NO305558703

MILEAGE

FUEL

E.....

R/MS

COMFORT TRANSPORTATION PTE LTD

7010045

JSTOMER NO. 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755 :L. (R)

(O)

06.2023 22:20 TARGET DATE

(P)

YR OF MANU. 28.07.2022

PRIUS HYBRID(G4A24.

CHASSIS CODE JTDKB3FU003096807

MAKE

MODEL

COMPLETION DATE/TIME:

....1/2.....

SCOUNT CARD NO


Accident Date: 24.06.2023 NATURE: 3P 24.06.2023

S/NO

LABOR CODE

DESCRIPTION

JOB DESCRIPTION



ECKED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE wledgement Slip Exit Pass Vehicle No.: SHA7770P YY € No.: SHA7770P

of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard

eturned to Service Reception upon collection