

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA3241B
MAKE HYUNDAI
MODEL IONIQ

DATE: 24.06.23
MVA JUMANI
DOA: 23.06.23

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT BUMPER ASSY			\$481.10
10	FRT BUMPER CHIPS			\$22.00
1	RADIATOR GRILLE			\$1,568.60
1	FRT BUMPER CENTRE MOULDING			\$368.50
1	RADIATOR GRILLE EMBLEM			\$31.30
	SUB TOTAL			\$2,471.50
	LESS 20%			\$494.30
	DISCOUNTED TOTAL			\$1,977.20
	FRT NUMBER PLATE			\$55.00
	SUB TOTAL			\$55.00
	Labour Charge			
	PANEL BEATING			\$400.00
	SPRAY PAINT			\$300.00
	TOTAL LABOUR			\$700.00
	ESTIMATE TOTAL			\$2,732.20
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tamplin 9749524
WSP

26/4/23 @ 11am

2 days

4/5 days after repair

Tamplin @ Juman

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5901554

JC NO305558667

OMER
S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


REGN NO.: SHA3241B	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 24.06.2023 09:20
YR OF MANU. 28.01.2021	TARGET DATE
CHASSIS CODE KMHC851CVLU192321	COMPLETION DATE/TIME:

JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 23.06.2023
ATURE: 3P.23.06.23

NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

dgement Slip

Exit Pass

SHA3241B JU INCOME

Vehicle No.: SHA3241B

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard