

REPAIR ESTIMATE*

VEHICLE NO SH 8608C

MAKE **HYUNDAI**

MODEL	IONIQ
-------	-------

DATE: 24.06.23

MVA JUMANI

DOA: 23.06.23

INCOME

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tungku 9749549 2 days
(wp) 26/6/23 e l l a n
4/5 rising after sunset
tungku c l h a n d o n

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date _____

Date/Time: 24.06.2023 10:11

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5901538

JC NO305558665


OMER
S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)
JUNT CARD NO.

REGN NO.: SH 8608C	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 24.06.2023 08:40
YR OF MANU. 02.07.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU164480	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 23.06.2023
ATURE: 3P.23.06.23

NO LABOR CODE DESCRIPTION



KEYED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Judgement Slip

Exit Pass

lo.: SH 8608C JU

Vehicle No.: SH 8608C

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard